

# OBJEDNÁVKA

k poskytnutí dílčího plnění služby  
č. 015 / 2017 / 155210247

## Servisní podpora letounu CL-601 3A Challenger poznávací značky [REDACTED]

Specifikace dílejšího plnění	Provedení prací na letounu v rozsahu 1. 1 až 1.6 pro plánovanou údržbu letounu CL-601 a dále dle bodů 2.1, 2.2, 2.5, 2.6, 2.7 a 2.8 specifikace Smlouvy v servisním středisku RUAG			
	Poř. čís.	Označení (P/N)	Název	Poznámka
	1	Pravidelná údržba	Viz příloha č.1 – bod <u>Tasks</u>	Požadované činnosti dle bodů 1 – 7. provést servisním střediskem RUAG ve dnech 3.7. až 6.9. 2017 včetně předání a převzetí letounu.
	2	Servisní Bulletin a nařízení	Viz příloha č.1 – bod <u>SB+AD</u>	
	3	Opravy interiéru a IFE	Viz příloha č.1 – bod <u>Interier +IFE</u>	
	4	Ostatní opravy	Viz příloha č.1 – bod <u>Other repairs</u>	
	5	Vícepráce vyplývající z technologických nálezů při provádění bodů 1 až 4. a provedení prací k zachování letové způsobilosti		
	6	Dodání dokumentace včetně změnové a školení personálu		
7	Zaslání požadovaných informací o provedení prací do systému CAMP			

Zpracoval kpt [REDACTED]

V Praze dne 18.4.2017

Nabídka dílejšího plnění	Poř. čís.	Označení (P/N)	Název	Cena v Kč bez DPH	Cena v Kč včetně DPH
	1		Pravidelná údržba	11 981 056,00	14 497 077,76
	2		Servisní Bulletin a nařízení		
	3		Opravy interiéru a IFE	5 984 000,00	7 240 640,00
	4		Ostatní opravy		
			<b>CELKEM</b>	<b>17 965 056,00</b>	<b>21 737 717,76</b>
Stanovisko zástupce objednatele k nabídce dílejšího plnění	Souhlasím <del>nesouhlasím</del> s nabídkou dílejšího plnění*)				
Místo předání předmětu dílejšího plnění	RUAG, SRN				
	Hodnost, jméno a příjmení převírajícího [REDACTED] (hůlkovým písmem)				

Místo provádění předmětu dílčího plnění	RUAG, SRN		
Termín zahájení dílčího plnění	čas / den/ měsíc / rok 3.7.2017		
Termín ukončení dílčího plnění	čas / den/ měsíc / rok 6.9.2017		
<b>Zástupce objednatele</b>		<b>Zástupce poskytovatele</b>	
Hodnost, jméno, příjmení: (hůlkovým písmem)		Jméno, příjmení: [REDACTED] (hůlkovým písmem) poradce prezidenta pro obchod	
Datum a podpis: [REDACTED] 20.6.2017		Datum a podpis: 15. 6 .2017 [REDACTED]	
Telefonické a faxové spojení: [REDACTED]		Telefonické a faxové spojení: [REDACTED]	

CAMPOT s.r.l.  
Nekázanka 880/11  
112 21 Praha 1  
IČO: 25063138 24

**Příloha č.1**

**Tasks:**

- 60 MO, 12 MO, 36 MO, tasks according to CAMP till 31<sup>st</sup> December 2017;
- 300 FH and FH tasks required till 100FH from handover to RUAG

**SB + AD:**

- SB 601-0612 – floor structure
- FAA AD 2014-15-13 + CF 2016-17R2 PART II + SB 601-0636 R1 – landing gear parts serialisation
- SB 601-0626 – HSTA pin serialisation
- SB 601-0640 – APU fuel negative-G line chaffing
- aircraft responders TDR-94D – works according to Bulletin for ADSB-OUT
- NZ-2000 (FMZ 2000) replacement CD-810 by CD-820 and sw.6.1 upgrade, including enhancement of FANS/CPDLC (Controller-pilot data link communications)
- navAero tBAG EFB computer module enhansment for WIN<sup>TM</sup>7 (memory 16GB, Core<sup>TM</sup> i7).

**Interior:**

- replacement of the carpet in passenger cabin;
- repair of seat-folding mechanisms, deep cleaning and color renewal of VIP seats;
- repair of seat-folding mechanisms, deep cleaning and painting renewal of passenger seats;
- partial (minor) repairs of „wood“ decoration WC, kitchen, partitions and side panels of passengers cabin and aircraft entrance section;
- repair of IFE (replacement of CRT TV by LED 17-inch display, replacement of videorecorders and CD/DVD player by 2 multimedia players (MP3, MP4, AVI, DIV-X, X-VID and USB flashdisk input. Installation of these players in the galley.
- repair of volume control (for passengers seats)



- aircraft position tracking information displayed on LCD;
- waste water tank reservoir – replacement with higher capacity (we would like at least 50% percent increase – depends on offer)

**Other repairs:**

- AFIS to NZ-2000 (FMZ 2000) together with CPDLC bulletin
- Ox.bottle hydrostatic test (required by CAMP)
- Fire extinguishers hydrostatic and weight tests (required by CAMP)
- MLG wheels Overhaul: JUN98-1188, SEP91-0404, JUN02-1819
- Doors between cargo and lavatory – seal replacement
- Manufacturing and attaching curtain (as a loose equipment) for JetBed seats + replacement of curtains behind the leather seats by the same curtain design
- Galley water panel - INNOTECH (EMPTY light does not work)
- ICS panel for navigator – repair of HF1 position switch