





Supplemental Agreement No: 


Subject of the agreement

This Supplemental Agreement No.  is made on 24 October 2016 between 






DULY SIGNED THIS SUPPLEMENTAL AGREEMENT AS OF THE DATE WRITTEN BELOW,



Czech Airlines Technics, a. s.



ax

M

Attachment No. 1

to the Supplemental Agreement No. 47

ADDITIONAL SERVICE REQUEST

Aircraft reg. PH-HZL

Heavy maintenance visit HMV8

Work Package difference between the quoted work package HMV8 and actual work package, according to the below mentioned overview of the Deleted and Added Tasks has been calculated as follows:

Routine / Customized / Additional Labour (added tasks)	EUR	21742,20
(expected findings within the gap of 50 Mhs included for Routine and Customized tasks only)		
Routine / Customized / Additional Labour (deleted tasks)	EUR	- 26268,30
Total Summary	EUR	- 4526,10

Credited to: Transavia

Ordered by: Transavia

Deleted Tasks:

Task card	20-142-03-01	24-110-00-01	26-550-02-01
28-181-00-01	32-290-00-01	33-070-00-01	34-100-00-01
38-015-00-01	47-210-00-01	49-172-00-01	52-220-00-01
52-460-00-01	53-110-00-01	53-140-00-01	53-140-00-02
53-150-00-01	53-160-00-01	53-240-00-01	53-250-00-01
53-360-00-01	53-360-00-02	53-360-00-03	53-360-00-04
53-380-00-01	53-390-00-01	53-800-00-01	53-868-00-01
53-878-00-01	53-886-00-01	54-015-01-01	54-015-02-01
54-070-01-01	54-070-02-01	54-080-01-01	54-080-02-01
57-070-01-01	57-070-02-01	57-280-01-01	57-280-02-01
23-08896-01	737-27A1277-1	INSPEC-53TAV-01348	MONTHLY
SERVICE CHECK	TAV20-120-01	TAV72-110-01	

Added Tasks (Routine, Custom):

Taskcard/WO	20-310-00-01	20-320-00-01	20-325-00-01
20-330-00-01	20-335-00-01	20-340-00-01	20-370-00-01
20-375-00-01	20-380-00-01	20-390-00-01	20-400-00-01
20-465-00-01	20-490-00-01	20-500-00-01	20-510-00-01
20-520-00-01	20-530-00-01	20-540-00-01	20-550-00-01
20-570-00-01	20-580-00-01	20-590-00-01	20-610-00-01
20-620-00-01	21-190-00-01	24-100-00-01	27-075-01-01
27-075-02-01	27-100-00-01	27-101-00-01	27-110-00-01

27-134-00-01	27-142-01-01	27-142-02-01	27-148-01-01
27-148-02-01	27-168-01-01	27-168-02-01	27-226-00-01
27-226-00-02	27-226-00-03	27-226-00-04	27-229-00-01
27-229-00-02	27-235-00-02	28-050-00-01	28-090-00-01
28-150-00-01	28-150-00-02	32-450-00-01	32-450-00-02
32-450-00-03	32-450-00-04	32-450-00-05	33-090-01-01
34-060-10-01	49-212-00-01	52-210-00-01	53-220-00-01
54-010-01-01	54-010-02-01	54-030-01-01	54-030-02-01
57-040-00-01	57-050-00-01	57-060-01-01	57-060-02-01
57-120-01-01	57-120-02-01	57-140-01-01	57-140-02-01
57-160-01-01	57-160-02-01	57-200-01-01	57-200-02-01
57-210-01-01	57-210-02-01	57-220-01-01	57-220-02-01
57-230-01-01	57-230-02-01	57-240-01-01	57-240-02-01
57-250-01-01	57-250-02-01	57-260-01-01	57-260-02-01
57-310-01-01	57-310-02-01	57-340-01-01	57-340-02-01
57-850-01-01	57-856-01-01	57-920-02-01	57-926-02-01
57-950-01-01	28-AWL-MOV	DAILY	INSPEC-11TAV-00019
INSPEC-11TAV-00020-1	INSPEC-46TAV-01277	INSPEC-72TAV-01160	INSPEC-72TAV-01160
MI 03692	TAV27-093-00	TAV70-806-01	TAV70-806-01
TAV70-806-01	TAV70-806-01	TAV74-020-01	TAV74-020-01
VARIOUS-53TAV-01269	INSPEC-38TAV-01371		

Added Tasks (AD, SB, MOD):

737-27-1273-1	737-32-1369-1	737-SL-54-021	737-SL-55-019
INSPEC-57TAV-01485	737-25-1641 WP6	737-25-1641 WP7	737-27-1291-1
737-32-1448-2LH	737-32-1448-2RH	737-32-1515	737-53-1335-LH
737-53-1335-RH	737-53A1248-1	737-53A1253	737-57A1314-1-LH
737-57A1314-1-RH	737-57A1327	737-SL-28-063-1	737-SL-28-096
737-SL-53-084-1	INSPEC-55TAV-01522		

Tasks excluded from the fixed price:

1	160186-1	INSPECTION HORIZONTAL STAB SKIN EXTERNAL REPAIR STA 129.5 RH
51	226371-1	GVI VAPOR BARRIER CRACK BETWEEN LBL 32 AND LBL 39
1	251121-1	FINAL REPAIR OF DAMAGED EGPR SURROUNDING STRUCTURE
1	N/R-00001	REF W/O 119602 T/C MI2008002 AND T/C INSPEC-12TAV-00179 CLEANING OF NLG AND MLG WHEEL WELLS. IT WAS FOR THOMS NOT POSSIBLE TO REALY CLEAN THESE WHEEL WELLS WITH THE BRUSH METHOD. SO A LOT OF TRAPPED DIRT BY CIC STAYED BEHIND. A NEW WHEEL WELL CLEAN HAS T
2	N/R-00002	FOUND DURING T/C: 57-872-02-01 REV8: RH WING, FLAP TRACK FAIRING #3 1X RIVET LOOSE ON SEAL. (AFT FAIRING RIGHT HAND)
3	N/R-00003	FOUND DURING PFC LOOSE RIVET ON RH INLET COWL.
4	N/R-00004	FOUND DURING HANGAR INSPECTION MAIN WHEEL WELL EXTREMELY DIRTY, WHOLE AREA IS SOAKED WITH OLD HYDRAULIC FLUID CAUSING DISSOLVING OF PAINT IN SEVERAL AREA'S. PLS MAKE PLANNING OF WHEEL WELL CLEAN ACC T/C IH-THOMS-WHEEL WELL; MI12008003 OR AMM TASK 12-40-00
5	N/R-00005	FOUND DURING LIGHTNING STRIKE INSP. (REF DR258405 WO 126818 N/R-00001) 2 LIGHTNING STRIKE DAMAGES ON NOSE RADOME UNDER THE PROTECTION BOOT. MARKED DAGAMES WITH # 14 AND # 15
6	N/R-00006	FOUND PUNCTURE 1/2 INCH X 1/2 INCH IN PANEL 193 AR (RH SIDE WING TO BODY FAIRING, PANEL BEHIND AFT INB FLAP WITH FLAPS UP): 11 INCH FROM THE FRONT SIDE OF THE PANEL AND APPROX 12 INCH FROM THE TOP MEASURED DOWN. PUNCTURE IS ONLY IN THE OUTER SKIN.





7	N/R-00007	CUSTOMER FINDING: EXTERNAL POWER DOOR, SURROUNDING CRACKED JUST UNDER LOWER HINGE
8	N/R-00008	REF DR 222825: DAMAGE TO THE RH WING TE PANEL SUPPORT STRUCTURE WAS REPAIRED AND THE LDG DOORS WERE ADJUSTED. DURING SERVICE CHECK, FOUND THE DOOR IS STILL DAMAGING THE PANEL STRUCTURE AT THE SAME LOCATIONS AS MENTIONED IN DR 222825

For and on behalf of
Transavia Airlines C. V.

Date: 26. October 2016
Name: Mr. Arnold Boot
Title: Director Purchasing & Logistics

Signature:



For and on behalf of
Czech Airlines Technics, a. s.

Date: 24 October 2016
Name: Mr. Pavel Haleš
Title: Chairman of the BoD

Signature:



Date: 24 October 2016
Name: Mr. Ivan Píkl
Title: Member of the Board of Directors

Signature:



