



Prague, P. O. 614, Box 35, Postcode 161 01 Czech Republic Phone (+420) 974 838 252 Fax (+420) 974 838 296 E-mail "let@mvcr.cz"

Ref. No. LS-2-52/ČJ-2019-9800KR

Prague 11.9.2019 No. of pages

AIRBUS HELICOPTERS **DEUTSCHLAND GmbH** Industriestr. 4 D-86609 Donauwörth **GERMANY**

ORDER

We request carrying out the exchange of the below mentioned item, ordered by our department, ref. No LS-2-52/ČJ-2019-9800KR:

P/N

S/N

STATIC INVERTER

SPC-10(HD)

821, 747

2 PC

Operates but generates INACTIVE signal

Helicopter EC135

S/N 0340

Please send the invoice with due date 30 days send to the recipient's address. In the invoice we need both following addresses:

Customer: Ministerstvo vnitra ČR

Nad Štolou 936/3 170 34 Praha 7

Recipient: Policie ČR letecká služba

pošta 614, schr. 35 161 01 Praha 6 IČO: 00007064 DIČ: CZ00007064

Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation

Department. The address is:

Delivery address:

Czech Police Aviation Department Airport Vaclav Havel south area Hangar "D"



Contract - LS-427-28/ČJ-2018-9800KR

Zakázka je vypořádána Rámcovou dohodou LS-427-28/ČJ-2018-9800KR k dodávce ND, oprav, modifikací, modernizace a služeb pro vrtulníky lehké hmotnostní kategorie EC 135

Vypracoval: Ing. Vypravil: Cirkvovo

Ulož. k č.j. Pot





LS PČR - oddělení nákupu

2-52

145 /5

Od:

Odesláno:

11. září 2019 12:50

Komu: Předmět: LS PČR - oddělení nákupu AW: LS-2-52/ČJ-2019-9800KR | MPN SPC-10(HD) | PN 771040

Dear Stanislava,

Repair:

Application	Price 2019	Pricing policy	Standard TAT	
Repair	1.608,00€	Fixed Price	78 days after receiving the part at AHD	

Exchange:

Application	Price 2019	Pricing policy	Availability
Exchange	2.272,00 €	Fixed Price	One part shall be available within 48 hours after receipt of your purchase order. No reservation possibility: Subject to prior sale.

FOD and scrap excluded.

Please return the defect part within 14 days at the latest. If we don't receive this part or may it appear that this unit is neither repairable nor has not been treated according to AIRBUS HELICOPTERS DEUTSCHLAND official maintenance documentation, AIRBUS HELICOPTERS DEUTSCHLAND reserves the right to revoke the credit note granted for this part.

Airbus Helicopters has not reserved these parts and reserves the right to sell these parts to the first one placing a purchase order. Please be so kind as to send us a filled out discrepancy form of your defect part attached to your exchange order so that we can proceed within standard regulations.

Please be informed that with immediate effect a subsequent invoice will follow in case the core unit has to be sent to the vendor for recertification due to missing documents (log card, EASA, document for parts which are no longer required).

This offer cancels and supersedes any previous quotation or offer made, whether oral or in written form. We look forward to receiving your answer as soon as possible.

Mit freundlichen Grüßen / Cordialement / Best regards



Key Logistics Manager CSOA



AKKA Germany GmbH on behalf of Airbus Helicopters Germany
AKKA Germany
Joseph-Gänsler-Straße 8c
86609 Donauwörth