



Prague, P. O. 614, Box 35, Postcode 161 01 Czech Republic Phone (+420) 974 838 252 Fax (+420) 974 838 296 E-mail "let@mvcr.cz"

Ref. No. LS-2-48/ČJ-2019-9800KR

Prague 11.9.2019 No. of pages 1

AIRBUS HELICOPTERS DEUTSCHLAND GmbH Industriestr. 4 D-86609 Donauwörth GERMANY

ORDER

We request carrying out the **exchange** of the below mentioned item, ordered by our department, ref. No LS-2-48/ČJ-2019-9800KR:

P/N S/N

FUEL SENSOR SUPPLY L284M30C1006 580 1 PC

Unreliable indication

Helicopter EC135 S/N 0499

Please send the invoice with due date 30 days send to the **recipient's address**. In the invoice we need both following addresses:

Customer: Ministerstvo vnitra ČR Recipient: Policie ČR letecká služba

Nad Štolou 936/3 pošta 614, schr. 35 170 34 Praha 7 161 01 Praha 6 IČO: 00007064 DIČ: CZ00007064

Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation

Department. The address is:

Delivery address:

Czech Police Aviation Department Airport Vaclav Havel south area Hangar "D"



Contract - LS-427-28/ČJ-2018-9800KR

Zakázka je vypořádána Rámcovou dohodou LS-427-28/ČJ-2018-9800KR k dodávce ND, oprav, modifikací, modernizace a služeb pro vrtulníky lehké hmotnostní kategorie EC 135

Vypracoval : Ing. (23)

Vypravil : Cirkvověří

Kontrola: Mgr. Maž. (15) E. 10.

Ulož. k č.j. Poče

Vyř. znak – Ihůta se 2024

LS PČR - oddělení nákupu

2-48

Od:

Odesláno: Komu: 11. září 2019 12:36 LS PČR - oddělení nákupu

Předmět:

AW: LS-2-48/ČJ-2019-9800KR | MPN L284M30C1006 | PN 1050043

Dear Stanislava,

Repair:

Application	Price 2019	Pricing policy	Standard TAT
Repair	1385,00€	Fixed Price	151 days after receiving the part at AHD

Exclusions: 12611

Exchange:

Application	Price 2019	Pricing policy	Availability
Exchange (1.676,00 EUR €	Fixed Price	One part shall be available within 48 hours after receipt of your purchase order. No reservation possibility: Subject to prior sale

FOD and scrap excluded.

53 hs

Please return the defect part within 14 days at the latest. If we don't receive this part or may it appear that this unit is neither repairable nor has not been treated according to AIRBUS HELICOPTERS DEUTSCHLAND official maintenance documentation, AIRBUS HELICOPTERS DEUTSCHLAND reserves the right to revoke the credit note granted for this part.

Airbus Helicopters has not reserved these parts and reserves the right to sell these parts to the first one placing a purchase order. Please be so kind as to send us a filled out discrepancy form of your defect part attached to your exchange order so that we can proceed within standard regulations.

Please be informed that with immediate effect a subsequent invoice will follow in case the core unit has to be sent to the vendor for recertification due to missing documents (log card, EASA, document for parts which are no longer required).

This offer cancels and supersedes any previous quotation or offer made, whether oral or in written form. We look forward to receiving your answer as soon as possible.

Mit freundlichen Grüßen / Cordialement / Best regards



Key Logistics Manager CSOA



AKKA Germany GmbH on behalf of Airbus Helicopters Germany AKKA Germany Joseph-Gänsler-Straße 8c