

**Bruker BioSpin MRI GmbH**

Rudolf-Plank-Str. 23  
 76275 Ettlingen  
 Deutschland  
 Tel: +49 (0)721 5161-6500  
 Fax: +49 (0)721 5161-6539  
 www.bruker.com

**Order Quotation: 8200019196**

Customer
Institute of Scientific Instruments of the ASCR, v.v.i. Kralovopolska 147 CZ-612 64 Brno

Bruker Contact	
Name	Ute Judisch
Telephone	015222971011
Fax	
E-mail	Ute.Judisch@bruker.com

Contact Person	
Name	
Tele:	
FAX	
E-mail	

Order Reference	
Quotation Start Date	24.09.2019
Quotation Validity	30 Days
Service Request	3000078706
Quotation Type	Estimated

Order Quotation Information			
Document date	24.09.2019	Currency	EUR
Incoterms	EXW Ettlingen	Prices	Excluding VAT
Payment Terms	At once, net cash	Instrument	10068072
Customer Number	1030325	Inst Desc	BIOSPEC 94/30 USR

Order Details						
Item	Product	Description	Qty	Unit price	Discount	Net price
10	A1409	Cold head maintenance 6 years	1,0	37.074,00	0,00	37.074,00
20	A1401	Labour time BSPS Exchange	4,0	215,00	0,00	860,00
30	W116790	BSPS 6 60 10/CB 2 shim power supply	1,0	27.600,00	0,00	27.600,00
Product Type : Repair exchange						
40	A1432	Accommodation	2,0	180,00	0,00	360,00
50	A1433-04	Travel Expenses	1,0	1.015,00	0,00	1.015,00
<b>Net Value (EUR)</b>						<b>66.909,00</b>



Pos. 10

Magnet maintenance System BioSpec 94/30 System Nr.:10068072

Due to the high load on individual components and the resulting wear and tear, this system requires regular maintenance.

In the 6th year of operation maintenance with the replacement of the cold head and the adsorber is required.

Required parts:

1841633 REFURBISHED COLDHEAD

1816095 F70 ADSORBER

1816093 FILTER UNIT WITH 1 METER FLEXLINE

The price for the maintenance includes labor and travel expenses, plus the legal value added tax valid on the day of delivery / service. The parts needed for maintenance as well as the required helium are included in the package price, other parts will be charged additionally if required.

Additional costs incurred, especially in case of quench or a required re-shimming of the magnet are also charged separately.

Delivery: to be agreed

Pricing (Incoterms 2010®): FCA Rheinstetten, Germany

Pos.20-50

The clearing will be done as per actual effort, but at least 1/2 service day plus travel, overnight costs and material. Every new hour will be billed as full hour. \*The quotation is only valid under the condition that the terms and conditions are accepted.

PLEASE NOTE: Bruker is not liable for damages caused through for the repair necessary current interruption of electricity. This could cause an electronical board damage # especially for older instruments. Please be prepared that this could mean unforeseen additional costs.

CAUTION: The customer is responsible to grant free and safe access to the instrument that is being repaired. It is mandatory to decontaminate the instrument from biological, radioactive and poisoned substances. If these regulations are not followed we will have the right to abort the repair and invoice the costs that have accrued.

Delivery: to be agreed

Pricing (Incoterms 2010®): FCA Rheinstetten, Germany

P.O./Inquiries: [helpdesk.bbiod@bruker.com](mailto:helpdesk.bbiod@bruker.com)

This is confidential information. It may not be passed on to third parties without written consent by Bruker. Bruker reserves the right in its sole and exclusive discretion to appoint a service engineer from Bruker or Bruker's affiliated companies.

Export conditions:

The customer understands that exports and re-exports of Bruker products and any related software, technical data, service, or technical assistance (individually, an #Item# and, collectively, the #Items#) are subject to U.S. and foreign trade controls, customs and economic sanctions laws, regulations, rules and orders (collectively, #Export Control Laws#). In addition to any other remedy it may have, Bruker may suspend and/or cancel the export, delivery, installation, and/or any maintenance or repair service of any Item if (a) Bruker has not received all export-related documentation requested by Bruker, including end-user certificates, (b) Bruker has not received the governmental approvals that Bruker deems to be required, or (c) Bruker believes that such activity may violate any Export Control Laws or Bruker's own compliance policies. Customer shall only use the Items for non-military, peaceful purposes. Customer shall not export, re-export or otherwise transfer or provide any Item in contravention of any Export Control



Law or any end-user certificate provided by Customer, including to an embargoed or otherwise sanctioned country. Customer must notify Bruker before providing any technical data to Bruker that is controlled under any Export Control Law. Bruker will not be liable to Customer for any loss or expense if Customer fails to comply with any Export Control Law. Customer shall indemnify Bruker for all losses, costs, claims, damages and expenses (including attorney fees and expenses) arising from Customer's violation or alleged violation of any Export Control Law.

NMR/CMR/EPR Service, SLS  
(electronic document - valid without signature)

---

Registered Office: Rheinstetten  
Registered Commercial Register: HRB Mannheim 102368  
Managing Directors: Dr. Falko Busse,  
Bernd Gleixner, Patrick Minhorst  
USt.-IdNr.: DE143 239 759

Deutsche Bank AG Karlsruhe  
Nr. 013 15 16 BLZ 660 700 04  
IBAN: DE87 6607 0004 0013 1516 00  
S.W.I.F.T.-BIC Deut DESM 660  
WEEE # Reg. Nr.: DE43181702