



Prague, P. O. 614, Box 35, Postcode 161 01 Czech Republic

Ref. No. LS-28-7/ČJ-2021-9800KR

Prague 26.2.2021

.2020

No. of pages 1

AIRBUS HELICOPTERS DEUTSCHLAND GmbH Industriestr. 4 D-86609 Donauwörth **GERMANY** 

## ORDER

We request carrying out the Exhange of the below mentioned item, ordered by our department, ref. No LS-28-7/ČJ-2021-9800KR:

> P/N S/N

**Z-ARIS** L633M2010107 1107 1 PC

**EXCHANGE** L633M2017101

Helicopter EC135 S/N 0424 TTSN: UNKNOWN

(4231:33)

Leak of the fluid

Please send the invoice with due date 30 days send to the recipient's address.

In the invoice we need both following addresses:

Nad Štolou 936/3

170 34 Praha 7

Customer: Ministerstvo vnitra ČR Recipient: Policie ČR letecká služba


> pošta 614, schr. 35 161 01 Praha 6 IČO: 00007064 DIČ: CZ00007064

Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation Department. The address is:

## **Delivery address:**

Czech Police Aviation Department Airport Vaclav Havel south area Hangar "D"



Contract - LS-427-28/ČJ-2018-9800KR

## LS PČR - oddělení nákupu

Od:

25. února 2021 10:04

Odesláno: Komu:

LS PČR - oddělení nákupu

Předmět:

AW: LS-2-7/ČJ-2021-9800KR \*exchange offer 45079\*

Dear ....

Many thanks for your request.

For PN in:L633M2010107 / PN out: L633M2017101 can offer you the following:

Application	Price 202	Pricing policy	Availability
Easy Exchange	11.987,00€	Fixed Price	One part shall be available within 48 hours after receipt of your purchase order. No reservation possibility: Subject to prior sale.

40475

## STANDARD EXCHANGE

Exchange used

Availability: Subject to prior sale!

This price offer remains valid until 25th April 2021

FOD and scrap excluded.

Please return the defect part within 14 days at the latest. If we don't receive this part or may it appear that this unit is neither repairable nor has not been treated according to AIRBUS HELICOPTERS DEUTSCHLAND official maintenance documentation, AIRBUS HELICOPTERS DEUTSCHLAND reserves the right to revoke the credit note granted for this part.

Airbus Helicopters has not reserved these parts and reserves the right to sell these parts to the first one placing a purchase order. Please be so kind as to send us a filled out discrepancy form of your defect part attached to your exchange order so that we can proceed within standard regulations.

Please be informed that with immediate effect a subsequent invoice will follow in case the core unit has to be sent to the vendor for recertification due to missing documents (log card, EASA, document for parts which are no longer required).

This offer cancels and supersedes any previous quotation or offer made, whether oral or in written form.

We look forward to receiving your confirmation as soon as possible.

Mit freundlichen Grüßen / Cordialement / Best regards

Key Logistics Manager CSOA Customer Service – Order Administration - CSOA MRO department – Civil Sector

