

We had a technical meeting with the staff that can make the welding job.

Depending on the parts design the place of welding need to be done from some different direction from what is stated in drawing.

It is not possible to weld from inside because of the already finished, welded design of the rectangular flanges.

Also the near areas with copper wire attached need to be cooled, protected during the welding process.

- We hereby quote 2350Euro for the remain welding mission that need to be done for the rectangularly flanges with the Tube.

With best regards

Peter Weisheit

Project Manager

Guismo Engineering s.r.o

Branická 213/53

Praha 4

Czech Republic

guismo engineering
production made easy ®

VAT reg. n CZ08409285

Corp. ID: CZ08409285

Domicile: Prague

Approved for VAT

Bank account 2181131518 /8040

Bank: Oberbank

BIC: OBKL CZ2X