



Ref. No. LS-3-97/ČJ-2022-9800KR

Prague 14.11.2022

No. of pages 2

SAFRAN Helicopter Engines Germany
Borsteler Chausse 43
22453 Hamburg
GERMANY

OrderWe are ordering the **repair** of the item below:

	S/N	pc
ENGINE ARRIUS 2B2	32086	1

Please send the invoice with due date 30 days you send to the **recipient's address**.

In the invoice we need both following addresses :


Customer : Ministerstvo vnitra ČR
Nad Štolou 936/3
170 34 Praha 7

Recipient : Policie ČR letecká služba
pošta 614, schr. 35
161 01 Praha 6
IČO : 00007064
DIČ : CZ00007064
Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation Department. The address is :

Delivery address:

Czech Police Aviation Department
Vaclav Havel Airport Prague
south area
Hangar "D"



Contract – 10/21/IG.FOS

**Zakázka je vypořádána Smlouvou o materiálně technickém zabezpečení
č. j. LS-758-24/Cj-2019-9800KR**

Vypracoval: 
Vypravil: 
Kontrola: 
Ulož. k č.j. Počet listů 6
Vyř. znak – Jhůta S- 2027

LS PČR - oddělení nákupu

Od: [REDACTED]
Odesláno: 15. listopadu 2022 10:39
Komu: [REDACTED]
Kopie: LS PČR - oddělení nákupu
Předmět: AW: Arrius 2B2 S/N 32086 - CPI-2022-05050 - LS-3-97

Dear [REDACTED]

M02 is the biggest part of this engine.


I can roughly estimate an amount of approx.. 285.000€ for an Overhaul with replacement of about 33% of the LLP's
Can be less or more.

Economic conditions of 2022.

Thanks and best regards,

[REDACTED]

Mit freundlichen Grüßen - Best regards - с уважением



SUBSCRIBE TO THE SAFRAN NEWS



Sitz der Gesellschaft: Hamburg

Amtsgericht Hamburg HRB 47905

Geschäftsführung: [REDACTED]

Bankverbindung: Deutsche Bank AG DE89 3607 0050 0113 1184 00

USt-ID: DE11868898



Hello [REDACTED]

I have just opened CPI-2022-05050 for repair of the engine 32086.

There is a request for transport box in the comment.

I understand it is not easy to estimate the price, but can you give us rough pricing for such kind of M02 repair?