



Ref. No. LS-2-55/ČJ-2023-9800KR

Prague 10.10.2023

No. of pages 2

**AIRBUS HELICOPTERS  
DEUTSCHLAND GmbH  
Industriestr. 4  
D-86609 Donauwörth  
GERMANY**

**ORDER**

We request carrying out the **repair** of the below mentioned item, ordered by our department, ref. No LS-2-55/ČJ-2023-9800KR:

	<b>P/N</b>	<b>S/N</b>	
<b>LANDING LIGHT</b> Movement sticks in both axes, IR filter cracked Helicopter EC135T2 S/N 0602	<b>0230154-002</b>	<b>071804</b>	<b>1 pc</b>
<b>LANDING LIGHT</b> Does not illuminate, faulty bulb sockets Helicopter EC135T2 S/N 0310	<b>45-0253-29</b>	<b>0111</b>	<b>1 pc</b>

Please send the invoice with due date 30 days send to the **recipient's address**.


In the invoice we need both following addresses :

**Customer :** Ministerstvo vnitra ČR  
Nad Štolou 936/3  
170 34 Praha 7

**Recipient :** Policie ČR letecká služba  
P.O.BOX č. 2  
163 00 Praha 618  
IČO : 00007064  
DIČ : CZ00007064  
Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation Department. The address is :

**Delivery address:**  
Czech Police Aviation Department  
Airport Vaclav Havel  
south area  
Hangar "D"



## LS PČR - oddělení nákupu

---

**Od:** [redacted] za uživatele Order-easy (AH) Contact  
**Odesláno:** 10. října 2023 11:49  
**Komu:** LS PČR - oddělení nákupu  
**Kopie:** [redacted]  
**Předmět:** Re: LS-2-55/ČJ-2023-9800KR  
**Přílohy:** image002.png; image002.png

Dear [redacted]

Please find enclosed OVH and REPAIR information for requested PN :

**- 0230154-002**

OVH : On quote

REPAIR : 3 375 euros with TAT of 100 days

**- 45-0253-29**

REPAIR : 4 587 euros with TAT of 120 days.

Do not hesitate if you require more information,



**Material & Logistics Service Center – Airbus Helicopters**

**Please send your material request to :**

- Brand name: [redacted]
- Repair a: [redacted]
- By the h: [redacted]
- Warrant: [redacted]
- AOG : [redacted]

Le jeu. 5 oct. 2023 à 09:03 [redacted] a écrit :

Dear,

We would like to ask you to send us a price quotation for the repair, overhaul – see attachment

Thank you very much

Best regards