



Institute of Organic Chemistry and Biochemistry of the CAS

Dr. Flemingovo nám. 2 166 10 Praha 6 Check Republic Quotation No. AC240301

Unterschleissheim, March 4th 2024

Quotation for the repair of 698.STP s/n 22011701W0698 at Gatan Inc, case# 28066 RMA 18440

Item Units	Description	Total in EUR
	We will invoice the real costs, which could be lower or higher.	
1	Parts required: Bottom shutter screw, clip, housing dewar, base insulation, Insulating wall, J5 Support, P5 conductor support	
2	Labor is for evaluation, repair, and test at € per hour hours estimated	
3	Freight and custom clearance Munich – Warrendale – Munich	
	Total	5.461,00

Evaluation Results: Holder recieved under vacuum. Bottom shutter screw missing. Barrel pushed in and rotated in the flange. Holder will have to be disassembled for repairs. Clamping on sample grid is loose. Crack in dewar housing of cryostation. Holder passed vacuum leak check and connects to temperature controller - reads 22.5°C. Supporting parts will need to be replaced. O rings will be replaced. The holder will be repaired, aligned and then tested to ensure proper functions. The holder will be leak checked, baked and freeze tested.

Validity of quotation: 60 days
Terms of payment: 30 days net

Transaction will be done after prior consultation and order entry.

Due to global supply chain issues, we cannot guarantee turnaround times for repairs. Some parts may be difficult to get and may have very long lead times.





A € evaluation fee will apply if the repair is refused after evaluation of the equipment, or the equipment is determined to be not repairable.

Commercial terms: EXW Unterschleissheim

General Terms and Conditions:

Our General Terms and conditions which are attached apply to all contracts of sale of any type and goods and services. Please note the applicable law and jurisdiction clause 11.

Ametek terms and conditions apply as attached.

With best regards Ametek GmbH Business Unit Gatan

Director of Service