

FEI Europe B.V. Sales & Service division · Achtseweg noord · P.O. BOX 80066 · NL-5600 KA Eindhoven

Bill-to address	CZ0003	•		
Ustav pristrojove techniky AV CR			Ustav pristrojove techniky Inst.of Scientific Instruments	
Kralovopolska 147			Kralovopolska 147	
		·	ktronove mikroskopie	
612 64 Brno		612 64	Brno	
Czech republic		Czech republic		
Ozecii republic		VAT Reg	CZ68081731	
Quotation no.:	0331aSS-11092017 / EU6	33991	11 September 2017	
Dear ,				
	d costs for the service by or	ur engineer on your MAGELLA	.N 400 (Serialnumber D9862)	
Specification:				
		440,000,00,00	1 140,000,00,07	
	On-site repair and alignment of the tool 148,000.00 CZK 1 148,000.00 CZK Working time, travel time & overnight			
vvolvang amo, acevo. amo	d overnight			
Total estimated cost			148,000.00 CZK	
Please submit a Purcha	ase Order for the total am	ount above or sign this quot	lation below and fax it back.	
Validation period	Validation period This quote is valid for 90 days from quotation date.			
Pricing terms The prices are net and subject to VAT, at the prevailing rate.				
J	•	•	· ·	
Payment terms 30 Days Ne		Net after invoice date		
		, i	Authorized signature / Date	
With best regards,				
FEI Europe B.v.				
			Name in print	
Fax: +420 2390 16469				
Tel: +420 2390 16467			PO Number / reference:	

KvK Eindhoven 17097158, VAT Registration nr. NL805698656B01 CZK: HSBC Prague, IBAN CZ8281500000002131003104, BIC MIDLCZPP

support.czech@fei.com

Mail:

_

Service rates 2017

Labor and travel rate:

 Labor and travel rate:
 4,160.00 CZK
 Per hour

 Overnight charge
 3,330.00 CZK
 Per day

 Daily rate
 40,770.00 CZK
 Per day

Labor and travel rate service contract customers:

Labor and travel rate: 3,536.00 CZK Per hour Overnight charge 3,330.00 CZK Per day

Daily rate: includes 9 hours of labor/travel and an overnight charge

Actual working hours will be invoiced according to service report.

Travel:

The maximum travel charge for one way is 2 hours.

The minimum travel charge per day is 1 hour.

Actual travel hours will be charged according to signed service report, with the exceptions listed above.