



Ref. No. LS-2-62/ČJ-2018-9800KR

Prague 16.8.2018

No. of pages 2

**AIRBUS HELICOPTERS  
DEUTSCHLAND GmbH  
Industriestr. 4  
D-86609 Donauwörth  
GERMANY**


**ORDER**

We request carrying out the **Exchange** of the below mentioned item, ordered by our department, ref. No LS-2-62/ČJ-2018-9800KR:

	P/N	S/N	
APMS	416-00298-010	534,1109	2 PC
<b>Broken ALT.A PB, Faulty HDG PB.</b>			


Please send the invoice with due date 30 days send to the **recipient's address**.  
In the invoice we need both following addresses :

**Customer :** Ministerstvo vnitra ČR  
Nad Štolou 936/3  
170 34 Praha 7

**Recipient :** Policie ČR letecká služba  
pošta 614, schr. 35  
161 01 Praha 6  
IČO : 00007064  
DIČ : CZ00007064  
Bank.spoj. 

Spare parts are to be delivered directly to our Police Aviation Department. The address is :

**Delivery address:**  
Czech Police Aviation Department  
Airport Vaclav Havel  
south area  
Hangar "D"




**Contract – PPR-21874-48/ČJ-2013-990656**

**Zakázka je vypořádána Smlouvou na dodávky ND, oprav a služeb pro vrtulníky EC 135  
č. j. PPR-21874-48/ČJ-2013-990656**



# LS PČR - oddělení nákupu

**Od:**   
**Odesláno:** 16. srpna 2018 9:51  
**Komu:** LS PČR - oddělení nákupu  
**Předmět:** AW: LS-2-62/ČJ-2018-9800KR  
**Přílohy:** image004.png



Many thanks for your request.

For PN 416-00298-010 I can offer you the following:

Application	Price 2018	Pricing policy	Standard TAT	EASY TAT
Repair	13.353 €	Fixed Price	320 days after receiving the part at AHD	45 days after receiving the part at AHD

Application	Price 2018	Pricing policy	Availability
Standard Exchange ✓	14.587 €	Fixed Price	Two parts should be available within 48 hours after receipt of your purchase order. No reservation possibility: Subject to prior sale.

BR,



*467 tis x 2 = 936 tis*

*35 300,54 € v DPH*



Key Logistics Manager  
Customer Service – Order Administration  
AKKA Germany GmbH



On behalf of Airbus Helicopters ESMCG/ESMCN



**Airbus Helicopters Deutschland GmbH**  
Industriestraße 4,  
86609 Donauwörth  
Deutschland

AIRBUS HELICOPTERS DEUTSCHLAND GmbH  
Vorsitzender des Aufsichtsrats: Guillaume Faury  
Geschäftsführung: Dr. Wolfgang Schoder (Vorsitzender),  
Thomas Hundt, Johannes Kleidorfer, Dr. Klaus Przemeck,  
Martin Schübel, Stefan Thomé