

Ref. No. LS-3-114/ČJ-2018-9800KR

Prague 30.10.2018

No. of pages 2

SAFRAN Helicopter Engines Germany
Borsteler Chausse 43
D-22453 Hamburg
GERMANY

Order

We are ordering the **overhaul** of the item below:

	S/N	pc
ENGINE ARRIUS 2B2	32145	1

Please send the invoice with due date 30 days you send to the **recipient's address**.

In the invoice we need both following addresses :

Customer : Ministerstvo vnitra ČR
Nad Štolou 936/3
170 34 Praha 7

Recipient : Policie ČR letecká služba
pošta 614, schr. 35
161 01 Praha 6
IČO : 00007064
DIČ : CZ00007064
Bank.spoj.



Spare parts are to be delivered directly to our Police Aviation Department. The address is :


Delivery address:


Czech Police Aviation Department
Vaclav Havel Airport Prague
south area
Hangar "D"



Contract – 27/16/IG.FOS

**Zakázka je vypořádána Smlouvou o materiálně technickém zabezpečení
č. j. LS-250-23/CJ-2016-9800KR**





OVERHAUL BUDGETARY QUOTATION

REF : **20-2018/IG-SHEG**

DATE: **29th October 2018**

FROM: **Safran Helicopter Engines GERMANY GmbH**

TO: **CZECH POLICE**

Dear [REDACTED]

This document is a budgetary quote and only displays estimated price for the overhaul of your item(s) and the exact price will depend on the status of the material at removal and following complete evaluation.

1. Equipment

Description of equipment: Arrius 2B2

S/N: 32145

Reason of removal: End of TBO

2. Service & pricing

Service requested: **OVERHAUL**

Release certificate requested: **EASA Form 1**

Price estimation:

Overhaul of 1 Arrius 2B2 (HMU incl.):

Approx. 292.900 EUR*

*: All prices are per engine, VAT excluded, on 2018 economic conditions and are quoted FCA SAFRAN HE. Prices are estimated prices and will be reviewed according to the findings on the material.

The price includes:

- Labour: disassembly, cleaning, inspection, balancing and reassembly excluding rework of parts
- Test: test cell fee (fuel and oil)
- Rework: corresponds to repair of engine parts in accordance with repair schemes of the manufacturer engine repair manual
- Systematic spare parts: low value items are systematically replaced
- Brand new parts: repairable parts are replaced by repaired parts
- Incorporation of the latest modification in accordance with Safran HE Repair Centre procedures

The price does **not** include:

- Life limited parts and usage limited parts.
- Missing part at arrival
- Damages due to poor maintenance, incorrect operation, abnormal wear (abnormal erosion, corrosion, overheating, surging...) or from the ingestion of foreign object (FOD)

Estimation duration: **The turnaround time for the Overhaul is approx. 3 months.**

APPENDIX: SPECIFIC TERMS & CONDITIONS

PAYMENT TERMS: As Per existing FOS contract Nr: 27/16/IG,FOS or Your ref: LS-250-23/CJ-2016-9800KR

QUOTATION:

This Budgetary quotation is considered as prices estimation and another quotation will be issued according to findings after complete inspection of the material.

For your information after issuing the quotation:

VALIDITY OF QUOTATION: 60 days