



Ref. No. LS-28-38/ČJ-2021-9800KR

Prague 9.7.2021

No. of pages 2

**AIRBUS HELICOPTERS
DEUTSCHLAND GmbH
Industriestr. 4
D-86609 Donauwörth
GERMANY**

ORDER

We request carrying out the **repair** of the below mentioned item, ordered by our department, ref. No LS-28-38/ČJ-2021-9800KR:

| | P/N | S/N | |
|----------------------------------|---------------|------------|-------------|
| CARTRIDGE | 130100 | 982 | 1 PC |
| Noisy, radio interference | | | |
| CARTRIDGE | 130100 | 995 | 1 PC |
| Does not operate | | | |
| Helicopter EC135 | | | |
| All | | | |

Please send the invoice with due date 30 days send to the **recipient's address**.

In the invoice we need both following addresses :


Customer : Ministerstvo vnitra ČR
Nad Štolou 936/3
170 34 Praha 7

Recipient : Policie ČR letecká služba
pošta 614, schr. 35
161 01 Praha 6
IČO : 00007064
DIČ : CZ00007064
Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation
Department. The address is :

Delivery address:

Czech Police Aviation Department
Airport Vaclav Havel
south area
Hangar "D"



Contract – LS-427-28/ČJ-2018-9800KR

**Zakázka je vypořádána Rámcovou dohodou LS-427-28/ČJ-2018-9800KR k dodávce ND,
oprav, modifikací, modernizace a služeb pro vrtulníky lehké hmotnostní kategorie
EC 135**

Vypracoval : 
Vypravil 
Kontrola: 
Ulož. k čj. Pocer. listu
Vyř. znak – lhůta S- 2026

LS PČR - oddělení nákupu

Od: 
Odesláno: 8. cervence 2021 16:11
Komu: 
Kopie: Contact, Repair (AHD)
Předmět: AW: LS-28-38/ČJ-2021-9800KR - SAP ID 1119937 - PN 130100 - SEM No. 47147 + 47148

Hello 

Thank you for your repair and exchange request of part number 130100. The available check for two exchange parts have been launched. I will come back to you again as soon I receive the results of the stock analyzes.

We are pleased to offer you the repair service as following:

| SAP ID | PN | Service | Price 2021 |
|---------|--------|-------------------|------------|
| 1119937 | 130100 | Repair with EXCL. | 1.163,00 € |

20 hrs - 200

*The exclusion ID's 20428/20430 may apply additionally.

REPAIR: **100** days after cost approval

Please be informed that the above mentioned price is an repair fixed price with exclusions. The work report can only be sent after the investigation is finished.

This offer is valid until the 8th of September 2021.

We are looking forward to hearing from you soon.

Best regards



Customer Service – Order Administration - CSOA
MRO department – Civil Sector
AKKA Germany GmbH

AKKA

On behalf of AIRBUS HELICOPTERS - ESMCG



Part time Working hours:

Tuesday till Friday 8:00 – 13:00

Monday out of office

Airbus Helicopters Deutschland GmbH
Industriestraße 4
86609 Donauwörth
Deutschland

AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Vorsitzender des Aufsichtsrats: Bruno Even
Geschäftsführung: Dr. Wolfgang Schoder (Vorsitzender),
Thomas Hundt, Johannes Kleidorfer, Dr. Klaus Przemec, Martin Schübel, Stefan Thomé
Sitz der Gesellschaft: Donauwörth
Register: Amtsgericht Augsburg, HRB 16508
USt. Ident.Nr./VAT reg.no DE 129273267


Von: [REDACTED]
Gesendet: Donnerstag, 8. Juli 2021 10:13
An: [REDACTED]
Cc: [REDACTED]
Betreff: LS-28-38/CJ-2021-9800KR

Dear [REDACTED]

We would like to ask you to provide us with your price quotation – **repair /Exchange/ - see attachment**
Helicopter EC135 - all

Thank you very much for your cooperation

Have a nice day



www.policie.cz

LETECKÁ SLUŽBA POLICIE ČR

Ekonomický odbor

p.ú.614, schr. 35,
161 01 Praha 6



Pomáhat a chránit

The information in this e-mail is confidential. The contents may not be disclosed or used by anyone other than the addressee. Access to this e-mail by anyone else is unauthorised. If you are not the intended recipient, please notify Airbus immediately and delete this e-mail. Airbus cannot accept any responsibility for the accuracy or completeness of this e-mail as it has been sent over public networks. If you have any concerns over the content of this message or its Accuracy or Integrity, please contact Airbus immediately. All outgoing e-mails from Airbus are checked using regularly updated virus scanning software but you should take whatever measures you deem to be appropriate to ensure that this message and any attachments are virus free.