

Prague, P. O. 614, Box 35, Postcode 161 01 Grech Republic Phone's Co. Faxt E-re

Ref. No. LS-28-41/ČJ-2021-9800KR

Prague 9.7.2021

No. of pages 2

AIRBUS HELICOPTERS DEUTSCHLAND GmbH Industriestr. 4 D-86609 Donauwörth GERMANY

## ORDER

We request carrying out the **repair** of the below mentioned item, ordered by our department, ref. No LS-28-41/ČJ-2021-9800KR:

P/N

S/N

MIXING VALVE

JBS880-3

T-M10082-04

1 PC

Does not operate

Helicopter EC135 All

Please send the invoice with due date 30 days send to the recipient's address.

In the invoice we need both following addresses:

Customer: Ministerstvo vnitra ČR

Nad Štolou 936/3 170 34 Praha 7 Recipient: Policie ČR letecká služba

pošta 614, schr. 35 161 01 Praha 6 IČO: 00007064 DIČ: CZ00007064


Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation

Department. The address is:

Delivery address:

Czech Police Aviation Department Airport Vaclav Havel south area Hangar "D"



Contract - LS-427-28/ČJ-2018-9800KR

Zakázka je vypořádána Rámcovou dohodou LS-427-28/ČJ-2018-9800KR k dodávce ND, oprav, modifikací, modernizace a služeb pro vrtulníky lehké hmotnostní kategorie EC 135

Vypracoval : Vypravil

Kontrola Vilož. k č.j. Počet listů 5 Vyř. znak – Ihůta S- 2026

## LS PČR - oddělení nákupu

Od:

Odesláno:

Komu:

Kopie:

Contact, Repair (AHD)

Předmět: Přílohy: AW: LS-28-41/ČJ-2021-9800KR - SAP ID 37128 - PN JBS880-3 - SEM No. 47146

Exclusion ID 19968.pdf



Thank you for your repair and exchange request of part number L284M30C1006. The available check for an exchange part has been launched. I will come back to you again as soon I receive the results of the stock analyzes.

We are pleased to offer you the repair service as following:

SAP ID	PN	Service	Price 2021
37128	JBS880-3	Repair	7.963,00 €

276 43

\*The exclusion ID 19968 may apply additionally. Attached you will find the associated designations for your review.

REPAIR: 250 days after cost approval

Please be informed that the above mentioned price is an repair fixed price with exclusions. The work report can only be sent after the investigation is finished.

This offer is valid until the 8th of September 2021.

We are looking forward to hearing from you soon

Mit freundlichen Grüßen / Cordialement / Best regards

Operational Team Leader
Customer Service – Order Administration - CSOA
MRO department – Civil Sector
AKKA Germany GmbH



On behalf of AIRBUS HELICOPTERS - ESMCG



Airbus Helicopters Deutschland GmbH Industriestraße 4 86609 Donauwörth Deutschland

AIRBUS HELICOPTERS DEUTSCHLAND GmbH

Vorsitzender des Aufsichtsrats: Bruno Even Geschäftsführung: Dr. Wolfgang Schoder (Vorsitzender), Thomas Hundt, Johannes Kleidorfer, Dr. Klaus Przemeck,

Martin Schübel, Stefan Thomé Sitz der Gesellschaft: Donauwörth

Register: Amtsgericht Augsburg, HRB 16508 USt. Ident.Nr./VAT reg no DE 129273267

Gesendet: Donnerstag, 8. Juli 2021 10:16

We would like to ask you to provide us with your price quotation - repair /Exchange/ - see attachment Helicopter EC135 - all

Thank you very much for your cooperation

Have a nice day



www.policie.cz LETECKÁ SLUŽBA POLICIE ČR

Ekonomický odbor

p.ú.614, schr. 35, 161 01 Praha 6



The information in this e-mail is confidential. The contents may not be disclosed or used by anyone other than the addressee. Access to this e-mail by anyone else is unauthorised.

If you are not the intended recipient, please notify Airbus immediately and delete this e-mail.

Airbus cannot accept any responsibility for the accuracy or completeness of this e-mail as it has been sent over public networks. If you have any concerns over the content of this

message or its Accuracy or Integrity, please contact Airbus immediately.

All outgoing e-mails from Airbus are checked using regularly updated virus scanning software but you should take whatever measures you deem to be appropriate to ensure that this message and any attachments are virus free