



Ref. No. LS-3-6/ČJ-2022-9800KR

Prague 1.2.2022

No. of pages 2

SAFRAN Helicopter Engines Germany
Borsteler Chausse 43
22453 Hamburg
GERMANY

OrderWe are ordering the **repair** of the item below:

	P/N	S/N	pc
HMU	0319850530	662B	1

Disassembled from engine after fuel leakage
TSN 3750:53 TSR 1270:38

Please send the invoice with due date 30 days you send to the **recipient's address**.

In the invoice we need both following addresses :


Customer : Ministerstvo vnitra ČR
Nad Štolou 936/3
170 34 Praha 7

Recipient : Policie ČR letecká služba
pošta 614, schr. 35
161 01 Praha 6
IČO : 00007064
DIČ : CZ00007064
Bank.spoj. 5504-881/0710

Spare parts are to be delivered directly to our Police Aviation Department. The address is :

Delivery address:

Czech Police Aviation Department
Vaclav Havel Airport Prague
south area
Hangar "D"



Contract – 10/21/IG.FOS

**Zakázka je vypořádána Smlouvou o materiálně technickém zabezpečení
č. j. LS-758-24/Čj-2019-9800KR**

Vypracoval: 
Vypravil: 
Kontrola: 
Ulož. k č.j. Počet listů 6
Vyř. znak – lhůta S- 2027

LS PČR - oddělení nákupu

Od: 
Odesláno: 25. ledna 2022 14:44
Komu: LS PČR - oddělení nákupu
Předmět: FW: ARS 2B2 - HMU removal due to leak

Dobré odpoledne,
mám tu ještě cenovou nabídku na HMU (viz níže). Máme cenu nového – pro porovnání?

Zase tam zdůrazňuji, že, pokud jsme schopni, tak máme dát požadavek v jejich systému.
Doplňte mi, prosím, číslo naší objednávky na HMU do tabulky a zkusím jim to do toho systému zadat. Ty RFQ a PO nevím, jestli jsou naše čísla, nebo si je přiřadí oni.

	S/N	LS	Lead Time	Price	RFQ No.	PO No.
ARRIUS 2B2	32144	LS-3-5/ČJ-2022-9800KR	120-150 Days	397.120 €	??	??
HMU 0319850530	662B			28.857 €		

Děkuji

S pozdravem


technický inspektor - drak a motor

LETECKÁ SLUŽBA POLICIE ČR

odbor technické inspekce
Letiště Václava Havla, hangár D
161 00 Praha 6, Ruzyně



Dear 

The price for overhaul of HMU will be 28.857€, this is the price for PN 0319850530. In case if during the Overhaul some specific TU will be applied and the PN number outbound will be changed, the price can slightly increase. The official end price offer you will receive after the HMU has arrived and the evaluation has been done in Repair Center.