

PRO:

Fyzikální ústav AVČR

[REDACTED]

Na Slovance 2
182 21 Praha 8

 ČÍSLO: **V22071510S**

 DATUM: **15. 7. 2022**

VYŘIZUJE: [REDACTED]

Servis Spectromag needle valve

POZ.	NÁZEV	MNOŽSTVÍ	CENA / MJ BEZ DPH	CENA CELKEM BEZ DPH
	Service vist to investigate needle valve issue (2 paid service days) Service vist to investigate needle valve issue (2 paid service days) Service visit to investigate and re-work needle valve including the following. - Re-tapping the needle valve body - Replacing the needle drive rod and associated o-rings - Leak checking of needle valve/ VTI circuit - Check and setup needle valve operation - System cooldown/testing as time allows This scope of work is offered on a 'best effort' basis and performance improvemnets cannot be guaranteed. The needle valve body is located inside the welded helium can and cannot be accessed on site. Therefore, if the needle valve body was to be damaged, the system may have to be returned and re-quoted.	1	162 200 Kč	162 200 Kč
	Replacement needle/drive rod with re-tapping tool	1	15 930 Kč	15 930 Kč

CELKEM BEZ DPH: 178 130,00 Kč

CELKEM DPH 21% 37 407,30 Kč

CELKEM VČETNĚ DPH: 215 537,30 Kč

Zastoupení a servis v ČR:

CHROMSPEC spol s r.o.,

Zapsána v obchodním rejstříku vedeném Městským soudem v Praze, oddíl C, vložka 5418

IČO: 44794053 DIČ: CZ44794053

[REDACTED]

Sídlo:

 Jindřicha Plachty 28,
 150 00 Praha 5, tel.:257324057

Registrované pobočky:

252 10 Mníšek pod Brdy, Lhotecká 594,

tel.:318599083, fax:318591529

634 00 Brno, Plachty 2

tel.:547246683, fax:547246685

e-mail: info@chromspec.cz

www.chromspec.cz

Vypracoval: [REDACTED]