



Ref. No. LS-2-29/ČJ-2024-9800KR

Prague 24.6.2024

No. of pages 2

**AIRBUS HELICOPTERS  
DEUTSCHLAND GmbH  
Industriestr. 4  
D-86609 Donauwörth  
GERMANY**

**ORDER**


We request carrying out the **repair** of the below mentioned item, ordered by our department, ref. No LS-2-29/ČJ-2024-9800KR:

	<b>P/N</b>	<b>S/N</b>	
<b>ICP-NVG</b>	<b>C19269AA</b>	<b>E1011</b>	<b>1 PC</b>
Helicopter EC135T2 S/N 0602			
Faulty controller BARO			
<b>BLOWER ASSY</b>	<b>JBS13016-11</b>	<b>K65949</b>	<b>1 PC</b>
Helicopter EC135T2 S/N 0602			
Short brushes			
<b>MIXING VALVE</b>	<b>JBS880-3</b>	<b>JBS880-3-430</b>	<b>1 PC</b>
Helicopter EC135T2 S/N 0348			
Does not operate			
<b>WARNING UNIT ASSY</b>	<b>L315M5004101</b>	<b>PL202</b>	<b>1 PC</b>
Helicopter EC135T2 S/N 0426			
AT 104% RPM gong audio. Only at HIGH ROTOR. Adjustment at 97% RPM impossible.			

Please send the invoice with due date 30 days send to the **recipient's address**.  
In the invoice we need both following addresses :

Spare parts are to be delivered directly to our Police Aviation  
Department. The address is :

**Delivery address:**  
Czech Police Aviation Department  
Airport Vaclav Havel  
south area  
Hangar "D"



**Contract – LS-565-35/ČJ-2022-9800KR**

**Zakázka je vypořádána Rámcovou dohodou LS-565-35/ČJ-2022-9800KR k dodávce ND,  
oprav, modifikací, modernizace a služeb pro vrtulníky lehké hmotnostní kategorie  
EC 135**

## LS PČR - oddělení nákupu

---

**Od:** [REDACTED]  
**Odesláno:** 21. června 2024 11:37  
**Komu:** [REDACTED]  
**Kopie:** LS PČR - oddělení nákupu  
**Předmět:** Re: LS-2-29/ČJ-2024-9800KR

[REDACTED]  
Regarding repair for PN C19269AA :  
Fixed price : 10141 EUR

Bien cordialement / Best regards

[REDACTED]  
Material & Logistics Service Center – Airbus Helicopters

Please send your material request to :

Le mer. 19 juin 2024 à 15:09, Order-easy (AH) [REDACTED]

Regarding repair for PN C19269AA :  
There is no information about this part, I'm going to check internally to see if the part can be repaired.

Regarding repair for PN JBS13016-11 :  
Price : 4512 EUR  
TAT : 100 days

Regarding repair for PN JBS880-3 :  
Price : 9272 EUR  
TAT : 250 days

Regarding repair for PN L315M5004101 :  
Fixed price with exclusions : 7521 EUR  
TAT : 120 days

Bien cordialement / Best regards