



Airbus Helicopters Deutschland GmbH
Industriestrasse 4
86609 Donauwörth
GERMANY

Repair Order No. 190442

Date:

28.04.2026

Supplier No.: 70001

Your Reference:

Our Reference:
e-mail:



LS-2-11/CJ-2026-9800KR


Pos	Part No. / Description	Quantity	Discount	Unit price	Total
1	23081-073 Starter Generator Warehouse: 19 S/N: P4024 For overhaul	1,00 EA			
2	L771M40C1013 TRIPLE INDICATOR RPM(NVIS G Warehouse: BO 17 S/N: 757 Main rotor speed indicator not working	1,00 EA			
3	0230154-002 LANDING LIGHT Warehouse: BO 15 S/N: 050918 It doesn't move, it doesn't retract, it is still lit.	1,00 EA			


Subtotal:

8.634,00 EUR

Repair Order No. 190442

Sum Carried Over:					8.634,00 EUR
Pos	Part No. / Description	Quantity	Discount	Unit Price	Total

Net Sum	8.634,00 EUR
Delivery Date:	28.12.2027
<p>Please send the invoice with due date 30 days, send to the recipient's address. In the invoice we need both following addresses:</p>	
<p>CUSTOMER Ministerstvo vnitra CR Nad Stolou 936/3; 170 34 Praha</p>	
<p>RECIPIENT Policie CR letecka sluzba P.O.BOX 2 163 00 Praha 618 ICO: 00007064; DIC: CZ00007064 Bank: 5504-881/0710</p>	
<p>DELIVERY ADDRESS Czech Police Aviation Department Airport Vaclav Havel, south area Hangar D 161 00 Prague 6, Czech Republic</p>	
<p>Contract - LS-565-35/CJ-2022-9800KR</p>	
<p>Zakazka je vypořádána Ramcovou dohodou LS-565-35/CJ-2022-9800KR k dodavce ND, oprav, modifikaci, modernizace a služeb pro vrtulníky lehké hmotnostní kategorie EC 135</p>	
<p>Fakturovana částka se liší od částky uvedené v objednávce v důsledku změny kurzu zahraniční měny. Přepočítání bylo provedeno na základě aktuálního směnného kurzu platného ke dni fakturace.</p>	
 ředitel Letecké služby PCR	
Released from [redacted] on 28.04.2026 at 12:06	



AIRBUS

RETURN MATERIAL AUTHORIZATION RMA Confirmation for Customer

These operations will be performed in accordance with Service Letter N°1567-00-02

CUSTOMER REFERENCE N° :

190442/1

Date :

04.05.2026

MATERIAL TO BE SHIPPED TO :

AIRBUS HELICOPTERS

5 avenue du Valquiou
93290 TREMBLAY-EN-FRANCE
France

AIRBUS HELICOPTERS CONTACT :

Company :

Name :

Dep :

Tel :

Fax :

e-mail :

RMA N° :

502455548



Eori Code : FR35238371500021 / HS Code : 85114000900

SERVICE REQUESTED

Repair

PROPERTY :

CLI

ISSUER :

Customer N° : 55010475

Company Address :

Czech Police

Aviation Department

Po Box 614 35

16101 PRAHA 6

Czech Republic

Name :

Department :

AIRCRAFT DATA :

AIRCRAFT TYPE	REGISTRATION N°	SERIAL N°	A/C TT AT DAMAGE	DATE OF DAMAGE
EC135		0340		..

COMPONENT DATA :

COMPLAINT QUANTITY	AIRBUS HELICOPTERS P/N	DESCRIPTION					
1	23081-073	23081-073\STARTER-GENERATOR (200A)					
MANUFACTURER'S P/N	SERIAL N°	CSN	CSO	CSR	TSN	TSO	TSR
23081-073	P4024						

Please note that the following documents are mandatory and have to be attached with your part

Log Card (FME)

RMA

REASON FOR RETURN :

Defect

DETAILED DESCRIPTION OF DEFECT :

For overhaul

Hausanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Industriestraße 4, 86609 Donauwörth

Postanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
86607 Donauwörth

Lieferanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Dr. Ludwig-Bölkow-Straße 3, 86609 Donauwörth

AIRBUS HELICOPTERS DEUTSCHLAND GmbH

Vorsitzender des Aufsichtsrats

Industriestraße 4, 86609 Donauwörth

86607 Donauwörth

Register: Amtsgericht Augsburg, HRB 16508

USt-Ident.Nr./VAT reg.no DE 129273267

Deutsche Bank AG, München

SWIFT: DEUT DE 33, IBAN: DE 67 70070010 0 190235200

UniCredit Bank AG, München

SWIFT: HYVE DE 33, IBAN: DE 31 70020270 000 2702100



These operations will be performed in accordance with Service Letter N°1567-00-02

CUSTOMER REFERENCE N° :

190442/2

Date : 28.04.2026

MATERIAL TO BE SHIPPED TO :

AIRBUS HELICOPTERS

5 avenue du Valquiou
93290 TREMBLAY-EN-FRANCE
France

AIRBUS HELICOPTERS CONTACT :

Company :

Name :

Dep :

Tel :

Fax :

e-m :

RMA N° :

502454048



Eori Code : FR35238371500021 / HS Code : 90291000900

SERVICE REQUESTED

Repair

PROPERTY :

CLI

ISSUER :

Customer N° : 55010475

Company Address :

Czech Police
Aviation Department
Po Box 614 35
16101 PRAHA 6
Czech Republic

Name :

Department :

Tel :

Fax :

e-m :

AIRCRAFT DATA :

AIRCRAFT TYPE	REGISTRATION N°	SERIAL N°	A/C TT AT DAMAGE	DATE OF DAMAGE
EC135		0424		..

COMPONENT DATA :

COMPLAINT QUANTITY	AIRBUS HELICOPTERS P/N	DESCRIPTION					
1	L771M40C1013	L771M40C1013\TRIPLE INDICATOR RPM(NVIS G					
MANUFACTURER'S P/N	SERIAL N°	CSN	CSO	CSR	TSN	TSO	TSR
DL457-161	757						

Please note that the following documents are mandatory and have to be attached with your part
RMA

REASON FOR RETURN :

Defect

DETAILED DESCRIPTION OF DEFECT :

Main rotor speed indicator not working

Hausanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Industriestraße 4, 86609 Donauwörth

Postanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
86607 Donauwörth

Lieferanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Dr. Ludwig-Bolkow-Straße 3, 86609 Donauwörth

AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Vorsitzender des Aufsichtsrats
Sitz der Gesellschaft: Donauwörth
Register: Amtsgericht Augsburg, HRB 16508
USt-Ident Nr/VAT reg no DE 129273267

Deutsche Bank AG, München
SWIFT: DEUT DE 33, IBAN: DE 67 70070010 0 190235200
UniCredit Bank AG, München
SWIFT: HYVE DE 33, IBAN: DE 31 70020270 000 2702100

AIRBUS


RETURN MATERIAL AUTHORIZATION RMA Confirmation for Customer

These operations will be performed in accordance with Service Letter N°1567-00-02

CUSTOMER REFERENCE N° : Date :

MATERIAL TO BE SHIPPED TO :

AIRBUS HELICOPTERS
5 avenue du Valquiou
93290 TREMBLAY-EN-FRANCE
France

AIRBUS HELICOPTERS CONTACT :
Company : 

RMA N° :



Eori Code : FR35238371500021 / HS Code : 94054910000

SERVICE REQUESTED
Repair

PROPERTY :
CLI

ISSUER :
Customer N° : 55010475
Company Address :
Czech Police
Aviation Department
Po Box 614 35
16101 PRAHA 6
Czech Republic

Name :
Department : 

AIRCRAFT DATA :

AIRCRAFT TYPE	REGISTRATION N°	SERIAL N°	A/C TT AT DAMAGE	DATE OF DAMAGE
EC135		0340		..

COMPONENT DATA :

COMPLAINT QUANTITY	AIRBUS HELICOPTERS P/N	DESCRIPTION					
1	0230154-002	0230154-002\LANDING LIGHT -29 200/400W					
MANUFACTURER'S P/N	SERIAL N°	CSN	CSO	CSR	TSN	TSO	TSR
0230154-002	50918						

Please note that the following documents are mandatory and have to be attached with your part
RMA

REASON FOR RETURN :
Defect

DETAILED DESCRIPTION OF DEFECT :
It doesn't move, it doesn't retract, it is still lit.


Hauptanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Industriestraße 4, 86609 Donauwörth

Postanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
86607 Donauwörth

Lieferanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Dr. Ludwig-Bolkow-Straße 3, 86609 Donauwörth



AIRBUS HELICOPTERS DEUTSCHLAND GmbH



Deutsche Bank AG, München
SWIFT: DEUTDE33, IBAN: DE 67 70070010 0 190235200
UniCredit Bank AG, München
SWIFT: HYVEDE33, IBAN: DE 31 70020270 000 2702100