



Airbus Helicopters Deutschland GmbH
Industriestrasse 4
86609 Donauwörth
GERMANY

Repair Order No. 190451

Date:

18.05.2026

Supplier No.: 70001

Your Reference:

Our Reference:
e-mail:



LS-2-16/CJ-2026-9800KR - MRA

Pos	Part No. / Description	Quantity	Discount	Unit price	Total
We request repair of following item					
1	L673M20A1005 MAIN ROTOR ACTUATOR Warehouse: BO ZEM S/N: 00400 TSN:4806:53 - damaged thread of TIE RODs - minor HYD leakage We request modification acc. to IN-4070-67 to ENHANCED MRA.	1,00 EA			

Subtotal:

55.132,00 EUR

Repair Order No. 190451

Sum Carried Over:					55.132,00 EUR
Pos	Part No. / Description	Quantity	Discount	Unit Price	Total

Net Sum	55.132,00 EUR
<p>Please send the invoice with due date 30 days, send to the recipient's address. In the invoice we need both following addresses:</p>	
<p>CUSTOMER Ministerstvo vnitra CR Nad Stolou 936/3; 170 34 Praha</p>	
<p>RECIPIENT Policie CR letecka sluzba P.O.BOX 2 163 00 Praha 618 ICO: 00007064; DIC: CZ00007064 Bank: 5504-881/0710</p>	
<p>DELIVERY ADDRESS Czech Police Aviation Department Airport Vaclav Havel, south area Hangar D 161 00 Prague 6, Czech Republic</p>	
<p>Contract - LS-565-35/CJ-2022-9800KR</p>	
<p>Zakazka je vporadana Ramcovou dohodou LS-565-35/CJ-2022-9800KR k dodavce ND, oprav, modifikaci, modernizace a sluzeb pro vrtulniky lehke hmotnostni kategorie EC 135</p>	
<p>Fakturovana castka se lisi od castky uvedene v objednavce v dusledku zmeny kurzu zahranicni meny. Preocet byl proveden na za... zu platneho ke dni fakturace.</p>	
<p>reditel Letecke</p>	
<p>Released from ... on 18.05.2026 at 07:42</p>	

AIRBUS

RETURN MATERIAL AUTHORIZATION RMA Confirmation for Customer

These operations will be performed in accordance with Service Letter N°1567-00-02


CUSTOMER REFERENCE N° : Date :

MATERIAL TO BE SHIPPED TO :

AIRBUS HELICOPTERS
5 avenue du Valquiou
93290 TREMBLAY-EN-FRANCE
France

AIRBUS HELICOPTERS CONTACT :
Company :
Name :
Dept :
Tel :
Fax :
e-mail :

RMA N° :



Eori Code : FR35238371500021 / HS Code : 85011099900

SERVICE REQUESTED
Repair

PROPERTY :
CLI

ISSUER :
Customer N° : **55010475**
Company Address :
Czech Police
Aviation Department
Po Box 614 35
16101 PRAHA 6
Czech Republic

Name :
Department :
Tel :
Fax :
e-mail :

AIRCRAFT DATA :

AIRCRAFT TYPE	REGISTRATION N°	SERIAL N°	A/C TT AT DAMAGE	DATE OF DAMAGE
EC135		0310		..

COMPONENT DATA :

COMPLAINT QUANTITY	AIRBUS HELICOPTERS P/N	DESCRIPTION
1	L673M20A1005	L673M20A1005\MAIN ROTOR ACTUATOR

MANUFACTURER'S P/N	SERIAL N°	CSN	CSO	CSR	TSN	TSO	TSR
S4-3000490	400						

Please note that the following documents are mandatory and have to be attached with your part
Log Card (FME) RMA

REASON FOR RETURN :
Defect

DETAILED DESCRIPTION OF DEFECT :
- damaged thread of TIE RODs#- minor HYD leakage

Hausanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Industriestraße 4, 86609 Donauwörth

Postanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
86607 Donauwörth

Lieferanschrift:
AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Dr Ludwig-Bölkow-Straße 3, 86609 Donauwörth

AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Vergleichen Sie das Aufdruckmuster mit dem Original.
Bitte bei Unklarheiten kontaktieren.
Register: Amtsgericht Augsburg, HRB 16508
USt-Ident.Nr./VAT reg no DE 129273267

Deutsche Bank AG, München
SWIFT: DEUT DE 33, IBAN: DE 67 70070010 0 190235200
UniCredit Bank AG, München
SWIFT: HYVE DE 33, IBAN: DE 31 70020270 000 2702100