

Příloha č. 2 smlouvy

FÚ / UP	Adresa	Výrobce	Typ	S / N	Rok pořízení	Poznámka
FÚ pro hl.m. Prahu	Štěpánská 28, Praha 1	Cisco	WS-C6509-E	SMC16430039	2012	Cisco Systems, Inc. Catalyst 6500 9-slotChassis System
		Cisco	WS-C6K-VTT-E	SMT1639A441	2012	VTT-E FRU 1
		Cisco	WS-C6K-VTT-E	SMT1639A434	2012	VTT-E FRU 2
		Cisco	WS-C6K-VTT-E	SMT1639A437	2012	VTT-E FRU 3
		Cisco	CLK-7600	SMT1633E562	2012	OSR-7600 Clock FRU 1
		Cisco	CLK-7600	SMT1633E562	2012	OSR-7600 Clock FRU 2
		Cisco	WS-X6748-GE-TX	SAL11477D5Y	2007	WS-X6748-GE-TX CEF720 48 port 10/100/1000mb Ethernet Rev. 2.6
		Cisco	WS-F6700-CFC	SAL11477BRK	2007	WS-F6700-CFC Centralized Forwarding Card Rev. 4.0
		Cisco	WS-X6348-RJ45V	SAL0627205R	2002	WS-X6348-RJ45V 48 port 10/100 mb RJ45 Rev. 6.92
		Cisco	WS-X6316-GE-TX	SAD0634004F	2002	WS-X6316-GE-TX 16 port GE RJ45 Rev. 1.3
		Cisco	WS-X6408A-GBIC	SAL0740MK4E	2003	WS-X6408A-GBIC 8 port 1000mb GBIC Enhanced QoS Rev. 3.0
		Cisco	WS-SUP720-3B	SAL12351F55	2008	WS-SUP720-3B 2 ports Supervisor Engine 720 Rev. 5.7
		Cisco	WS-SUP720	SAL123405KF	2008	WS-SUP720 MSFC3 Daughterboard Rev. 3.2
		Cisco	WS-F6K-PFC3B	SAL12341053	2008	WS-F6K-PFC3B Policy Feature Card 3 Rev. 2.4
		Cisco	WS-SUP720-3B	SAL12448JL6	2008	WS-SUP720-3B 2 ports Supervisor Engine 720 Rev. 5.7
		Cisco	WS-SUP720	SAL124486YR	2008	WS-SUP720 MSFC3 Daughterboard Rev. 3.2
		Cisco	WS-F6K-PFC3B	SAL1243752R	2008	WS-F6K-PFC3B Policy Feature Card 3 Rev. 2.4
		Cisco	WS-X6516A-GBIC	SAL114999QL	2007	WS-X6516A-GBIC SFM-capable 16 port 1000mb GBIC Rev. 4.6
		Cisco	WS-X6724-SFP	SAL1546V8E1	2011	WS-X6724-SFP CEF720 24 port 1000mb SFP Rev. 5.0
		Cisco	WS-F6700-CFC	SAL1621D7KL	2012	WS-F6700-CFC Centralized Forwarding Card Rev. 4.1
		Cisco	WS-C6509-E-FAN	DCH1640004G	2012	Enhanced 9-slot Fan Tray 1
		Cisco	WS-CAC-3000W	SNI1631AX5T	2012	AC power supply, 3000 watt 1
		Cisco	WS-CAC-3000W	SNI1631AX61	2012	AC power supply, 3000 watt 2
		Cisco	N5K-C5548P	SSI15510GX4	2011	Nexus5548 Chassis
		Cisco	N5K-C5548P	FOC16225090	2012	O2 32X10GE/Modular Supervisor
		Cisco	N5548P-FAN			Chassis fan module
		Cisco	N5548P-FAN			Chassis fan module
		Cisco	N55-PAC-750W	POG16287TPG	2012	
		Cisco	N55-PAC-750W	POG16287TT1	2012	
		Cisco	N55-DL2	FOC1629628D	2012	O2 Non L3 Daughter Card
		Cisco	N2K-C2248TP-1GE	SSI16220AXD	2012	N2K-C2248TP-1GE CHASSIS
		Cisco	N2K-C2248TP-1GE	FOC16253Y75	2012	Fabric Extender Module: 48x1GE, 4x10GE Supervisor
		Cisco	N2K-C2248-FAN			Fabric Extender Fan module
		Cisco	N2200-PAC-400W	DTN1624P364	2012	Fabric Extender AC power supply
		Cisco	N2200-PAC-400W	DTN1624P368	2012	Fabric Extender AC power supply
		Cisco	N2K-C2248TP-1GE	SSI16220AWQ	2012	N2K-C2248TP-1GE CHASSIS
		Cisco	N2K-C2248TP-1GE	FOC16253YEQ	2012	Fabric Extender Module: 48x1GE, 4x10GE Supervisor
		Cisco	N2K-C2248-FAN			Fabric Extender Fan module
		Cisco	N2200-PAC-400W	DTN1624P394	2012	Fabric Extender AC power supply
		Cisco	N2200-PAC-400W	DTN1624P395	2012	Fabric Extender AC power supply

		Cisco	N5K-C5548P	SSI15430ELZ	2011	Nexus5548 Chassis
		Cisco	N5K-C5548P	FOC15451QVV	2011	O2 32X10GE/Modular Supervisor
		Cisco	N5548P-FAN			Chassis fan module
		Cisco	N5548P-FAN			Chassis fan module
		Cisco	N55-PAC-750W	ART1545X020	2011	AC power supply
		Cisco	N55-PAC-750W	ART1545X09L	2011	AC power supply
		Cisco	N55-DL2	FOC15451U40	2011	O2 Non L3 Daughter Card
		Cisco	N2K-C2248TP-1GE	SSI154307V4	2011	N2K-C2248TP-1GE CHASSIS
		Cisco	N2K-C2248TP-1GE	FOC1546474Z	2011	Fabric Extender Module: 48x1GE, 4x10GE Supervisor
		Cisco	N2K-C2248-FAN			Fabric Extender Fan module
		Cisco	N2200-PAC-400W	LIT15441UGJ	2011	Fabric Extender AC power supply
		Cisco	N2200-PAC-400W	LIT15441UKF	2011	Fabric Extender AC power supply
		Cisco	N2K-C2248TP-1GE	SSI15420L5V	2011	N2K-C2248TP-1GE CHASSIS
		Cisco	N2K-C2248TP-1GE	FOC15453Y6R	2011	Fabric Extender Module: 48x1GE, 4x10GE Supervisor
		Cisco	N2K-C2248-FAN			Fabric Extender Fan module
		Cisco	N2200-PAC-400W	LIT15430TLJ	2011	Fabric Extender AC power supply
		Cisco	N2200-PAC-400W	LIT15430TLK	2011	Fabric Extender AC power supply
		Cisco	WS-C2960S-48LPS-L	FOC1634W00W	2012	
		Cisco	WS-C2960X-48LPS-L	FOC1833S2EN	2014	
		Cisco	WS-C2960S-48TS-L	FOC1628W51U	2012	
		Cisco	WS-C3560G-48PS-S	FOC1344Y6R8	2009	
		Cisco	WS-C3560G-48PS-S	FOC1343Y6Y5	2009	
		Cisco	WS-C2960X-48LPS-L	FOC1833S2FZ	2014	
		Cisco	WS-C3560G-48PS-S	FOC1344Y6QM	2009	
		Cisco	WS-C2960S-48LPS-L	FOC1634W03A	2012	
		Cisco	WS-C3560G-48PS-S	FOC1344Y6QQ	2009	
		Cisco	WS-C2960S-48TS-L	FOC1629Z3NX	2012	
		Cisco	WS-C3560G-48PS-S	FOC1344Y6UT	2009	
		Cisco	WS-C2950G-48-EI	FCZ0943X11E	2005	
		Cisco	WS-C2950G-48-EI	FOC0620X19K	2002	
		Cisco	WS-C2960G-48TC-L	FOC1236V174	2008	
		Cisco	WS-C4507R	FOX073904LE	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE0738280Y	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411MMK	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074200KH	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074203YQ	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MQ2	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M32	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420DE6	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE073106D3	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4306-GB	JAE0743027G	2003	1000BaseX (GBIC) with 6 1000 GBIC ports
		Cisco	WS-X4306-GB	JAE1131SJUS	2007	1000BaseX (GBIC) with 6 1000 GBIC ports
		Cisco	WS-X4597	NWG073503C5	2003	FanTray

		Cisco	PWR-C45-1300ACV	SNIO733ABAM	2003	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNIO734AA6A	2003	Power Supply (AC 1300W)
		Cisco	WS-C2960X-48TS-L	FCW1833B0PH	2014	
		Cisco	WS-C2960G-48TC-L	FOC1141ZDAX	2007	
		Cisco	WS-C2960S-48TS-L	FOC1628W50R	2012	
		Cisco	WS-C2960S-24TS-L	FOC1629Y1S9	2012	
		Cisco	WS-C2950G-48-EI	FOC0735W3PB	2003	
		Cisco	WS-C2950G-48-EI	FOC0734Y241	2003	
		Cisco	WS-C2950G-48-EI	FOC0632Y1TE	2002	
		Cisco	WS-C2950G-48-EI	FOC0633W1S2	2002	
		Cisco	WS-C2950G-48-EI	FOC0633Y0BU	2002	
		Cisco	WS-C2950G-48-EI	FOC0735W3P4	2003	
		Cisco	WS-C2950G-48-EI	FOC0633Z0BD	2002	
		Cisco	WS-C2950G-48-EI	FOC0735X3J7	2003	
		Cisco	WS-C2950G-48-EI	FOC0633Z1F7	2002	
		Cisco	WS-C2950G-48-EI	FCZ0922Y01R	2005	
		Cisco	WS-C2950G-48-EI	FOC0735W3PD	2003	
ÚP pro Prahu 2	Vinohradská 49, Praha 2	Cisco	WS-C4507R	FOX073904LF	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE073827VW	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411MFF	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M99	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074203L4	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074200P6	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MCY	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420DJ7	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE07341EPE	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4597	NWG073503LV	2003	FanTray
		Cisco	PWR-C45-1300ACV	SNIO734AAFF	2003	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNIO734AA6H	2003	Power Supply (AC 1300W)
		Cisco	WS-C2950G-48-EI	FOC0734Y1QR	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3NZ	2003	
		Cisco	WS-C2950G-48-EI	FOC0735X3HY	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3P6	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3P3	2003	
ÚP pro Prahu 3	Drahobejlova 48, Praha 9	Cisco	WS-C4507R	FOX091205BS	2005	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE10170V21	2006	Clock Module
		Cisco	WS-X4590	JAE1020248G	2006	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590	JAE1020247Q	2006	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590	JAE1021300S	2006	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590	JAE1021302G	2006	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590	JAE1021307S	2006	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE0943P5Q3	2005	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE102133PZ	2006	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports

		Cisco	WS-X4597	NWG091503Y2	2005	FanTray
		Cisco	PWR-C45-1300ACV	SNI0951ARAR	2005	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNI0945AR7R	2005	Power Supply (AC 1300W)
		Cisco	WS-C2950G-48-EI	FOC0733Y2H0	2003	
		Cisco	WS-C2950G-24-EI	FOC0625X0SW	2002	
		Cisco	WS-C2950G-48-EI	FOC1027X29R	2006	
		Cisco	WS-C2950G-48-EI	FOC1051ZJ05	2006	
		Cisco	WS-C3548-XL	FAB0538U371	2001	
		Cisco	WS-C3548-XL	FAB0536M058	2001	
ÚP pro Prahu 4	Budějovická 7, Praha 4	Cisco	WS-C4507R	FOX073904LT	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE0738284S	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411M75	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M2G	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074203UF	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M8C	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MMC	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420CZQ	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE07341ER7	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4597	NWG073503J1	2003	FanTray
		Cisco	PWR-C45-1300ACV	SNI0734AADU	2003	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	DTM14070070	2010	Power Supply (AC 1300W)
		Cisco	WS-C2950G-48-EI	FOC0735X3HX	2003	
		Cisco	WS-C2950G-48-EI	FCZ0921Y2BB	2005	
		Cisco	WS-C2950G-48-EI	FOC0735X3J0	2003	
		Cisco	WS-C2950G-48-EI	FOC0903X1HJ	2005	
		Cisco	WS-C2950G-48-EI	FOC0734Z247	2003	
		Cisco	WS-C2950G-48-EI	FOC0903X1H9	2005	
		Cisco	WS-C2950G-48-EI	FOC0735W3PE	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3PJ	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3P7	2003	
		Cisco	WS-C2950G-48-EI	FCZ0922X01J	2005	
		Cisco	WS-C2960S-48TS-L	FOC1744Z0FR	2013	
ÚP pro Prahu 5	Peroutkova 61, Praha 5	Cisco	WS-C4507R	FOX073903TM	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE073007WB	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411MHQ	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MHT	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074207KN	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M4B	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M3H	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420C2C	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE073100N5	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4597	NWG073802BX	2003	FanTray
		Cisco	PWR-C45-1300ACV	SNI1443ARFM	2010	Power Supply (AC 1300W)

		Cisco	PWR-C45-1300ACV	SNIO736AA85	2003	Power Supply (AC 1300W)
		Cisco	WS-C2960S-48TS-L	FOC1739Y1A7	2013	
		Cisco	WS-C2960S-48TS-L	FOC1739Y12R	2013	
		Cisco	WS-C2950G-48-EI	FOC0735X3HW	2003	
		Cisco	WS-C2950G-48-EI	FCZ0912W0CG	2005	
		Cisco	WS-C2950G-48-EI	FOC0735W3Q8	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3PC	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3P5	2003	
		Cisco	WS-C2950G-48-EI	FOC0735X3J3	2003	
		Cisco	WS-C2950G-48-EI	FOC0735X3J5	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3PG	2003	
ÚP pro Prahu 6	Nábřeží Kap. Jaroše 7, Praha 7	Cisco	WS-C4507R+E	FOX1435GJLZ	2010	Cisco Systems, Inc. WS-C4507R+E 7 slot switch
		Cisco	WS-X4K-CLOCK-E	NWG143207RZ	2010	Clock Module
		Cisco	WS-X4590-EX=	NWG143300EJ	2010	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG143300TY	2010	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG143300PH	2010	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG143300WV	2010	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG14330135	2010	Mux Buffers for Redundancy Logic
		Cisco	WS-X4648-RJ45V+E	JAE1445106T	2010	10/100/1000BaseT (RJ45)+V E Series with 48 10/100/1000 baseT Premium PoE ports (Cisco/IEEE)
		Cisco	WS-X4624-SFP-E	JAE144601Q7	2010	1000BaseX (SFP) with 24 SFP Ports Jumbo Frame Support
		Cisco	WS-X45-SUP6-E	JAE144700A3	2010	Supervisor 6-E 10GE (X2), 1000BaseX (SFP) with 2 10GE X2 ports
		Cisco	CVR-X2-SFP	FDO1446154Y	2010	Converter Module
		Cisco	CVR-X2-SFP	FDO14460JCU	2010	Converter Module
		Cisco	WS-X4597+E	FOX1435G4XH	2010	FanTray
		Cisco	PWR-C45-1300ACV	SN11436AV9V	2010	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SN11427AV4G	2010	Power Supply (AC 1300W)
		Cisco	WS-C2960X-48LPS-L	FCW1930B578	2015	
		Cisco	WS-C2960S-48TS-L	FOC1742W1JS	2013	
		Cisco	WS-C2960S-48TS-L	FOC1742W1GQ	2013	
		Cisco	WS-C2960S-48LPS-L	FOC1634W03W	2012	
		Cisco	WS-C2950G-48-EI	FCZ1018W0NY	2006	
		Cisco	WS-C2950G-48-EI	FOC0738X0CV	2003	
		Cisco	WS-C2950G-48-EI	FOC0733Y2GU	2003	
		Cisco	WS-C2950G-48-EI	FOC0623W0UW	2002	
		Cisco	WS-C2950G-48-EI	FCZ1042X0TS	2006	
ÚP pro Prahu 7	Nábřeží Kap. Jaroše 7, Praha 7	Cisco	WS-C4507R	FOX11320AAA	2007	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE1132THUP	2007	Clock Module
		Cisco	WS-X4590	JAE1136W8OR	2007	Mux Buffers for Redundancy Logic
		Cisco	WS-X4591	JAE1136W9BL	2007	Mux Buffers for Redundancy Logic
		Cisco	WS-X4592	JAE1136W9JU	2007	Mux Buffers for Redundancy Logic
		Cisco	WS-X4593	JAE1136W9BT	2007	Mux Buffers for Redundancy Logic
		Cisco	WS-X4594	JAE1136VZGU	2007	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE114749GY	2007	Supervisor IV with 2 1000BaseX GBIC ports

		Cisco	WS-X4548-GB-RJ45	JAE11463A70	2007	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	PWR-C45-1300ACV	DTH1104N008	2007	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SN1124AS7D	2007	Power Supply (AC 1300W)
		Cisco	WS-C2960X-24PS-L	FOC1841S0HQ	2014	
		Cisco	WS-C2950G-48-EI	FOC0620X2CA	2002	
		Cisco	WS-C2950G-48-EI	FOC0622X0B6	2002	
		Cisco	WS-C2950G-48-EI	FOC0622X1H5	2002	
		Cisco	WS-C3560G-48PS-S	FOC1344Y6QR	2009	
ÚP pro Prahu 8	Trojská 13a, Praha 8	Cisco	WS-C4507R	FOX073904JX	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE073827F7	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411MC9	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MNR	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MFM	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MKW	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MEE	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420DJG	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE07350B5F	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4597	NWG073503SD	2003	FanTray
		Cisco	PWR-C45-1300ACV	SN10736AA9B	2003	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SN10736AA94	2003	Power Supply (AC 1300W)
		Cisco	WS-C2960S-48TS-L	FOC1741Z0KU	2013	
		Cisco	WS-C2950G-48-EI	FOC0734Y16E	2003	
		Cisco	WS-C2950G-48-EI	FOC0734Y1QH	2003	
		Cisco	WS-C2950G-48-EI	FOC0734Z29E	2003	
		Cisco	WS-C2950G-48-EI	FOC0734Z1W1	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3P1	2003	
ÚP pro Prahu 9	Drahobejlova 48, Praha 9	Cisco	WS-C4507R	FOX091502TB	2005	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE0919BXCP	2005	Clock Module
		Cisco	WS-X4K-MUX	JAE0922DWTW	2005	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE0922E3MH	2005	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE0918BHFR	2005	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE0918BH9P	2005	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE0919C30L	2005	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE0926FCQR	2005	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4597	NWG091205PF	2005	FanTray
		Cisco	PWR-C45-1300ACV	SN10924AR8H	2005	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SN10924AR87	2005	Power Supply (AC 1300W)
		Cisco	WS-C3548-XL	FAA0441W0CV	2000	
		Cisco	WS-C2950G-48-EI	FOC0730X1HB	2003	
		Cisco	WS-C3548-XL	FAB0538U1Q4	2001	
		Cisco	WS-C2950G-48-EI	FOC0622X0A7	2002	
		Cisco	WS-C3548-XL	FAB0538U26S	2001	
		Cisco	WS-C3548-XL	FAA0441X0CL	2000	

		Cisco	WS-C3548-XL	FAB0534V1PQ	2001	
		Cisco	WS-C2950G-48-EI	FHK0632W0R1	2002	
ÚP pro Prahu 10	Petrohradská 6, Praha 10	Cisco	WS-C4507R	FOX073904LE	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE0738280Y	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411MMK	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074200KH	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074203YQ	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MQ2	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M32	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420DE6	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE073106D3	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4306-GB	JAE0743027G	2003	1000BaseX (GBIC) with 6 1000 GBIC ports
		Cisco	WS-X4306-GB	JAE1131SIJUS	2007	1000BaseX (GBIC) with 6 1000 GBIC ports
		Cisco	WS-X4597	NWG073503C5	2003	FanTray
		Cisco	PWR-C45-1300ACV	SNIO733ABAM	2003	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNIO734AA6A	2003	Power Supply (AC 1300W)
		Cisco	WS-C2960G-48TC-L	FOC1141ZDBT	2007	
		Cisco	WS-C2960S-48TS-L	FOC1739Y18X	2013	
		Cisco	WS-C2950G-48-EI	FCZ0943X11D	2005	
		Cisco	WS-C2950G-48-EI	FCZ1051X05J	2006	
		Cisco	WS-C2950-12	FCZ0929W05H	2005	
		Cisco	WS-C2950G-48-EI	FOC0844X33J	2004	
		Cisco	WS-C2950G-48-EI	FHK0606Y0CH	2002	
		Cisco	WS-C2950G-48-EI	FOC0735W3P2	2003	
		Cisco	WS-C2950G-12-EI	FHK0830Y0BA	2004	
		Cisco	WS-C2950G-48-EI	FCZ0943Y133	2005	
		Cisco	WS-C2950G-48-EI	FOC0735W3P8	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3PA	2003	
		Cisco	WS-C2950-12	FCZ0929Y043	2005	
		Cisco	WS-C2950G-48-EI	FOC0633X01K	2002	
		Cisco	WS-C2950G-48-EI	FOC0735W3P0	2003	
		Cisco	WS-C2950G-48-EI	FOC0735W3PL	2003	
		Cisco	WS-C2950G-48-EI	FOC0902W047	2005	
ÚP pro Prahu 11	Opatovská 18, Praha 11	Cisco	WS-C4507R	FOX073904LU	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE0738285P	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411M9V	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M8Z	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411M95	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074207HQ	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074207K0	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420DJ1	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE07341ERB	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4148-RJ	JAE07400BJ0	2003	10/100BaseTX (RJ45) with 48 10/100 baseT ports

		Cisco	WS-X4148-RJ	JAE07400BKX	2003	10/100BaseTX (RJ45) with 48 10/100 baseT ports
		Cisco	WS-X4148-RJ	JAE07400C1R	2003	10/100BaseTX (RJ45) with 48 10/100 baseT ports
		Cisco	WS-X4597	NWG073503R7	2003	FanTray
		Cisco	PWR-C45-1300ACV	SNI1412AS4M	2010	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNI0734AAFJ	2003	Power Supply (AC 1300W)
		Cisco	WS-C2960G-48TC-L	FOC1234U4Y1	2008	
		Cisco	WS-C2950G-48-EI	FOC0844X33K	2004	
		Cisco	WS-C2960S-48TS-L	FOC1739Y14Z	2013	
ÚP pro Prahu 12	Lehárova 2, Praha 12	Cisco	WS-C4507R	FOX073904PG	2003	Cisco Systems, Inc. WS-C4507R 7 slot switch
		Cisco	WS-X4K-CLOCK	JAE073827GQ	2003	Clock Module
		Cisco	WS-X4K-MUX	JAE07411M3L	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074200CM	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MB5	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE074200P4	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4K-MUX	JAE07411MLR	2003	Mux Buffers for Redundancy Logic
		Cisco	WS-X4515	JAE07420C2U	2003	Supervisor IV with 2 1000BaseX GBIC ports
		Cisco	WS-X4548-GB-RJ45	JAE07350AVJ	2003	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4148-RJ	JAE0740076A	2003	10/100BaseTX (RJ45) with 48 10/100 baseT ports
		Cisco	WS-X4148-RJ	JAE074008S3	2003	10/100BaseTX (RJ45) with 48 10/100 baseT ports
		Cisco	WS-X4148-RJ	JAE07400C90	2003	10/100BaseTX (RJ45) with 48 10/100 baseT ports
		Cisco	WS-X4448-GB-RJ45	JAB064706HJ	2002	10/100/1000BaseT (RJ45) with 48 10/100/1000 baseT ports
		Cisco	WS-X4597	NWG073503KH	2003	FanTray
		Cisco	PWR-C45-1300ACV	SNI0734AAE4	2003	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNI0734AA6D	2003	Power Supply (AC 1300W)
SFÚ	Nábřeží Kap. Jaroše 7, Praha 7	Cisco	WS-C4507R+E	FOX1536GLG4	2011	Cisco Systems, Inc. WS-C4507R+E 7 slot switch
		Cisco	WS-X4K-CLOCK-E	NWG153306Z0	2011	Clock Module
		Cisco	WS-X4590-EX=	NWG15300AU4	2011	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG15300BFZ	2011	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG1530084W	2011	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG153009TU	2011	Mux Buffers for Redundancy Logic
		Cisco	WS-X4590-EX=	NWG15300BBQ	2011	Mux Buffers for Redundancy Logic
		Cisco	WS-X4648-RJ45V+E	JAE15430B1I	2011	10/100/1000BaseT (RJ45)+V E Series with 48 10/100/1000 baseT Premium PoE ports (Cisco/IEEE)
		Cisco	WS-X4612-SFP-E	JAE184907KC	2014	1000BaseX (SFP) with 12 SFP Ports Jumbo Frame Support
		Cisco	WS-X45-SUP6-E	JAE153700G5	2011	Supervisor 6-E 10GE (X2), 1000BaseX (SFP) with 2 10GE X2 ports
		Cisco	CVR-X2-SFP	FDO15331W4P	2011	Converter Module
		Cisco	CVR-X2-SFP	FDO15331W7Q	2011	Converter Module
		Cisco	WS-X4612-SFP-E	JAE184907NY	2014	1000BaseX (SFP) with 12 SFP Ports Jumbo Frame Support
		Cisco	WS-X4597+E	FOX1533GDED	2011	FanTray
		Cisco	PWR-C45-1300ACV	SNI1533ATNR	2011	Power Supply (AC 1300W)
		Cisco	PWR-C45-1300ACV	SNI1519AT55	2011	Power Supply (AC 1300W)
		Cisco	WS-C3560G-48PS-S	FOC1343Y6XU	2009	
		Cisco	WS-C2960G-48TC-L	FOC1141ZDBW	2007	
		Cisco	WS-C2960G-48TC-L	FOC1141ZDDP	2007	

		Cisco	WS-C2960X-48LPS-L	FCW1841A5DX	2014	
		Cisco	WS-C2960G-48TC-L	FOC1141ZDBP	2007	
		Cisco	WS-C2960G-48TC-L	FOC1141ZDFD	2007	
		Cisco	WS-C2960G-48TC-L	FOC1141ZD4X	2007	
		Cisco	WS-C2960G-48TC-L	FOC1143Z4GA	2007	
		Cisco	WS-C2960G-48TC-L	FOC1143Z4PC	2007	
		Cisco	WS-C2960G-48TC-L	FOC1610X4BU	2012	
		Cisco	WS-C2960S-24TS-L	FOC1629Y1RC	2012	
		Cisco	WS-C2950G-48-EI	FOC0633Y0BN	2002	
		Cisco	WS-C2950G-48-EI	FOC0633Z0C0	2002	
		Cisco	WS-C2960G-48TC-L	FOC1141ZCLX	2007	
		Cisco	WS-C2950G-48-EI	FOC0633Z0BQ	2002	
		Cisco	WS-C2960X-48TS-L	FCW1903B5BQ	2015	
		Cisco	WS-C2960X-48TS-L	FCW1903B5BZ	2015	
		Cisco	WS-C2960X-48TS-L	FCW1903B5AS	2015	
		Cisco	WS-C2960X-48TS-L	FCW1845A13Z	2014	
		Cisco	WS-C2960G-24TC-L	FOC1242W2S5	2008	
DTP Českomoravská	Českomoravská 29, Praha 9	Cisco	WS-C3550-12T	CAT0825N4T7	2004	
		Cisco	WS-C2960X-48TS-L	FCW1833A46T	2014	
		Cisco	WS-C2950G-48-EI	FOC0733Y1E1	2003	
		Cisco	WS-C2950G-48-EI	FOC0633Z1E7	2002	
SFÚ Petrohradská	Petrohradská 16, Praha 10	Cisco	WS-C3750X-24T-L	FDO1719H0FD	2013	WS-C3750X-24
		Cisco	C3KX-PWR-350WAC	DCB170994MF	2013	FRU Power Supply
		Cisco	C3KX-NM-1G	FDO17370M7W	2013	FRULink 1G Module
		Cisco	WS-C2960S-48TS-L	FOC1742W1CA	2013	
		Cisco	WS-C2960S-48TS-L	FOC1742W1JY	2013	