



Ref. No. LS-2-2/ČJ-2018-9800KR

Prague 23.1.2018

No. of pages 2

**AIRBUS HELICOPTERS
DEUTSCHLAND GmbH
Industriestr. 4
D-86609 Donauwörth
GERMANY**

ORDER

We request carrying out the **EASY repair** of the below mentioned item, ordered by our department, ref. No LS-2-2/ČJ-2018-9800KR:

	P/N	S/N	
MAIN ROTOR ACTUATOR (Assembly)	L673M20A1005	00371	1 pc
External leak of the HY fluid			
TTSN: 2496:09 II			
TSRepair: 1335.26II			

Please send the invoice with due date 30 days send to the **recipient's address**.

In the invoice we need both following addresses :

Customer : Ministerstvo vnitra ČR
Nad Štolou 936/3
170 34 Praha 7

Recipient : Policie ČR letecká služba
pošta 614, schr. 35
161 01 Praha 6
IČO : 00007064
DIČ : CZ00007064
Bank.spoj. 


Spare parts are to be delivered directly to our Police Aviation Department. The address is :

Delivery address:

Czech Police Aviation Department
Airport Vaclav Havel
south area
Hangar "D"

Ing. Tomáš HYTYCH

Czech Police Aviation Department



Contract – PPR-21874-48/ČJ-2013-990656

**Zakázka je vypořádána Smlouvou na dodávky ND, oprav a služeb pro vrtulníky EC 135
č. j. PPR-21874-48/ČJ-2013-990656**

Vypracoval : Ing. Prokšán

Vypravil : Cirkvová

Kontroloval: Mgr. Majdán, Jonáš

Ulož. k č.j. Počet listů 5

Vyř. znak – lhůta S- 2023



LS PČR - oddělení nákupu

Od: LOY2, Kathrin (AKKA GERMANY GMBH)
Odesláno: 22. ledna 2018 11:28
Komu: LS PČR - oddělení nákupu
Předmět: AW: LS-2-2/ČJ-2018-9800KR



Hello Stanislava,

Many thanks for your request.

For PN L673M20A1005 I can offer you the following:

Application	Price 2017	Pricing policy	Standard TAT	EASY TAT
Repair	51.880,00 €	Fixed Price	251 days after receiving the part at AHD	45 days after receiving the part at AHD

Please confirm costs and tell me which option you prefer.

BR,
Kathrin

Kathrin Loy
Key Logistics Manager
Customer Service – Order Administration
AKKA Germany GmbH



On behalf of
Airbus Helicopters
ESMCG/ESMCN

Airbus Helicopters Deutschland GmbH
Industriestraße 4,
86609 Donauwörth
Deutschland

AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Vorsitzender des Aufsichtsrats: Guillaume Faury
Geschäftsführung: Dr. Wolfgang Schoder (Vorsitzender),
Thomas Hundt, Johannes Kleidorfer, Dr. Klaus Przemeck,
Martin Schübel, Stefan Thomé
Sitz der Gesellschaft: Donauwörth
Register: Amtsgericht Augsburg, HRB 16508
USt-Ident.Nr./VAT reg.no DE 329273267

Von: 
Gesendet: Montag, 22. Januar 2018 06:57