



Ref. No. LS-2-56/ČJ-2018-9800KR

Prague 13.8.2018

No. of pages 2

**AIRBUS HELICOPTERS
DEUTSCHLAND GmbH
Industriestr. 4
D-86609 Donauwörth
GERMANY**

ORDER

We request carrying out the **EASY repair** of the below mentioned item, ordered by our department, ref. No LS-2-56/ČJ-2018-9800KR:

	P/N	S/N	
ALTIMETER	3A43.32.20F.28.4.EE	1042526	1 PC
Backlight inoperative			


Please send the invoice with due date 30 days send to the **recipient's address**.
In the invoice we need both following addresses :

Customer : Ministerstvo vnitra ČR
Nad Štolou 936/3
170 34 Praha 7

Recipient : Policie ČR letecká služba
pošta 614, schr. 35
161 01 Praha 6
IČO : 00007064
DIČ : CZ00007064
Bank.spoj. 


Spare parts are to be delivered directly to our Police Aviation Department. The address is :

Delivery address:
Czech Police Aviation Department
Airport Vaclav Havel
south area
Hangar "D"



Contract – PPR-21874-48/ČJ-2013-990656

**Zakázka je vypořádána Smlouvou na dodávky ND, oprav a služeb pro vrtulníky EC 135
č. j. PPR-21874-48/ČJ-2013-990656**



LS PČR - oddělení nákupu

Od: 
Odesláno: 9. srpna 2018 11:30
Komu: LS PČR - oddělení nákupu
Předmět: AW: LS-2-56/ČJ-2018-9800KR
Přílohy: image004.png; 4358_0001.pdf



Many thanks for your request.

For PN 3A43.32.20F.28.4.EE I can offer you the following:

Usage	Price 2018	Price policy	Availability/TAT
Standard Exchange	8.225 €	Fixed Price w. EXCL: 9275/9277 Designation MPN Exclusion: ALTITUDE COUNTER DIAPHRAGM	One part shall be available within 48 hours after receipt of your purchase order. No reservation possibility: Subject to prior sale.
EASY Repair	6.301 € ✓ <i>203 tps</i>	Fixed Price w. EXCL: 9275/9277 Designation MPN Exclusion: ALTITUDE COUNTER DIAPHRAGM	Standard TAT: 203 days after receiving the part at AHF EASY TAT: 45 days after ✓ receiving the part at AHF



Key Logistics Manager
Customer Service – Order Administration
AKKA Germany GmbH



On behalf of **Airbus Helicopters ESMCG/ESMCN**



Airbus Helicopters Deutschland GmbH
Industriestraße 4,
86609 Donauwörth
Deutschland

AIRBUS HELICOPTERS DEUTSCHLAND GmbH
Vorsitzender des Aufsichtsrats: Guillaume Faury
Geschäftsführung: Dr. Wolfgang Schoder (Vorsitzender),
Thomas Hundt, Johannes Kleiderfer, Dr. Klaus Przemeck,
Martin Schübel, Stefan Thomé
Sitz der Gesellschaft: Donauwörth