



Order of Calibration

Client	Geological Survey of Estonia F.R. Kreutzwaldi 5 44314 Rakvere, Estonia [REDACTED]
Client's representative person	[REDACTED] [REDACTED]
Location of calibration	Calibration laboratory – radon chambre, Kamenná 71, 262 31 Milín, Czech Republic
Devices to be calibrated:	
1. RM-2: sampling system ERM-3 (one piece) ionisation chambers (one case, 15 pieces)	1200 EUR
2. Markus 10, serial number 1306 (one piece)	415 EUR
3. Markus 10, serial number 1307 (one piece)	415 EUR
	Total: 2030 EUR

Date of issue: 09.02.2024

Geological Survey of Estonia